

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO. 40949		COMMENTS			
DATE RECEIVED 11/30/90	DATE OPENED 12/06/90	DATE CODE LF 2-85	SERIAL NUMBER B6674968	MODEL AND GRADE 700 22-250	BDL	ORDER R 90-317	
ACCESSORIES W/STUDS		SCOPE BASE					

FROM:

NAGEL'S GUN SHOP
6201 SAN PEDRO AVE.
SAN ANTONIO TX 78216

SHIP TO:

NAGEL'S GUN SHOP
6201 SAN PEDRO AVE.
SAN ANTONIO TX
78216

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRÉD

CUSTOMER'S REQUEST

"Smiter rifle fuselage bolt is closed, trigger pull not smooth"

MAIN FAULT

1) Bolt release tab broken 2) safety arm has been ground outside of factory - can lift only 1002"
altered component!

PARTS

Send repair quotation for new trigger assembly at 1/2 normal cost - gesture of good-will.

Product Service returning trigger assembly

REPAIRMAN JAB	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/8