

RECEIVING AND ESTIMATING REPORT							
INITIAL FJB		CUSTOMER ORDER NO.		COMMENTS HOG 05-2		SIGNATURE	
DATE RECEIVED 04/23/90	DATE OPENED 05/02/90	DATE CODED EE 119-BA	SERIAL NUMBER 10637556	MODEL AND GRADE 700 30-06	BDL	ORDER R 9013240	
ACCESSORIES W/STUDS							
FROM: NORTHWEST SHOOTER'S AND WOODSTOVE SUPPLY INC. 4786 HOLTON ROAD TWIN LAKE MI 49457				SHIP TO: NORTHWEST SHOOTER'S AND WOODSTOVE SUPPLY INC. 4786 HOLTON ROAD TWIN LAKE MI 49457			
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 5-7-90	VIA UPS		
REPAIR CHARGE							
TAX		INSURANCE		UPS		PARCEL POST	
TOTAL							
GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED							
CUSTOMER'S REQUEST: Gun fires, which safety is put from Safe to fire							
MAIN FAULT: Inside of trigger assembly rusted from unknown source - internal trigger parts are not moving properly							
PARTS				Replace trigger assembly at no charge. Product Team retaining trigger assembly for further investigation. 5/9/90 JAS.			
REPAIRMAN R.B.A.		PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	DATE	

RD6925 REV 6 88