

R 93-09805

INITIAL	CUSTOMER ORDER NO.				
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
4/12/93	04/14/93	XU 12-71	6501534		700 22-250 BDL
ACCESSORIES					
W/STUDS SCOPE BASE					
L/REAR SIGHT					

FROM:

Set up full

NORTHWESTERN INDUSTRIES
416 W MAIN
LEON A PYTLIK
VALLEY CITY

ND 58072

SHIP TO:

NORTHWESTERN INDUSTRIES
416 W MAIN
LEON A PYTLIK
VALLEY CITY

ND 58072

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				4/29/93	UPS
IN CONDITION			REPAIR CHARGE		
NEW			EXCISE 25.00		
LIGHTLY WORN			TAX		
WORN			INSURANCE		
VERY WORN			UPS		
UNREPAIRABLE			PARCEL POST		
MARRED			TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1				
IGGER GROUP		B2			E1	F1
LT ASSY.					E2	F2
REL ASSY.		B3		D1	E3	F3
C. ASSY.		B5		D2	E4	F4
OD			C1	D3	E5	F5
TAL			C2			

FAULT

*Upon receipt rifle is inspected. Found per following from notes
that is about 3000 rounds that all 3 trigger adjustment screws
have been tampered with outside the factory. No contact on adjustment
(chamber), not contact between barrel adjustment screw.*

COMMENTS

*Repair trigger assembly complete
and then adjust it to normal
adjustment test at gallery of yard
and.*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/82