

RECEIVING AND ESTIMATING REPORT

R 91-26548

INITIAL JJM	CUSTOMER ORDER NO.				
DATE RECEIVED 12/13/91	DATE OPENED 12/18/91	DATE CODE DE 9-84	SERIAL NUMBER 86633886	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06 ADL


TX 78372

ORANGE GROVE FIREARMS
P O BOX 301
ORANGE GROVE
USA 783

78372

CUST NO: 054944 C.E.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE		REPAIR CHARGE
		EXCISE
		TAX
		INSURANCE
		UPS
		PARCEL POST
TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	46um Bids when bolt is locked down - accidental misfire					
BOLT ASSY.						
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT 80 received. Bolt would not work at all. Disassembly of upper valve
inside of trigger assembly is contaminated with gummy substance.
Bear safety cam was sticking to side plate of trigger assembly. Both
of action and outside of trigger assembly very dirty. Bolt not
operating properly because of gummy substance on surface.

[illegible]

OFFICE COPY

RD6925 REV. 8

BARBER - Kinzer PPS GAL RE0003717

PPS 03712