

RECEIVING and ESTIMATE REPORT

ORDER R 28870

Form No. 10-1-79 ESTIMATED 1-28-80 VIA MAP CHARGES
FROM OZARK SHOOTERS INC
1719 COLLEGE SPRINGFIELD MO.

MODEL and GRADE 700 222 Rem SERIAL NO. A6524535 DATE CODE RQ
GRADE CODE 11-78

OR COMPUTER REFER. ONLY WITH scope Base REPAIR CHG 80-55
INS. PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quar)

CUSTOMER'S COMPLAINT

Fired while unloading

MAIN FAULT

Trigger catch adjust - not side of
factory.

GALLERY REPORT

DEMERIT
CODE

26655 - Trigger Housing after
17017 Ejector
17019 11 spec.

Relief Chamber

weep down

(Clean) (Test) (Target)

Repairman

JAN 31 1980