


1210
 paul associates
 engineers — surveyors — planners
 381 Middlebury Road (Conn. Rt. 64)
 Middlebury, Connecticut 06762



RECEIVED

NOV 11 1983

J.A. STEKL

TO

Remington Arms Co.
 Bridgeport, CT.
 06602

SUBJECT

Rem. Model
 Seven, SN. 7610930

.243 cal.

FOLD

An excellent rifle with one annoying feature — the bolt can be opened with the safety on "safe". I realize this safety feature was probably built in to protect you from the hungry lawyers. However, during hunting, the bolt, being as smooth as it is, keeps opening at the slightest touch on the bolt handle. This annoying feature negates the other positive qualities of the rifle. Can this problem be solved with a new safety — maybe