




Rayco Sales

9105 Mendenhall Mall
Juneau, AK 99801
907-789-4862

Remington Arms Inc.
Jim Stekl
Products Service
14 Hoefler Ave
Elion, NY 13357

JIM -

REM. 700 BDL 30-06 SN. 368540

This rifle discharged while the owner was raising the bolt handle to extract a cartridge. The rifle had been in the safe position and then moved to the fire position before the bolt was opened.

The gun discharged in the pilot house of the owners boat, the bullet went thru the deck, cut a fuel line next to the fuel tank and the imbedded in a frame member.

NO INJURIES

Thank you!

R. Shutt