

P.I.V. 53 GUN EXAMINATION REPORT NUMBER: 528 MODEL: 700
 GENERAL CONDITION: FAIR S. #: 23771
 OUTSIDE WORK: SIGHT REMOVED, RECOIL PAD AND DATE: 10-2-81
SWIVEL STUDS ADDED TECH: CAL REDDICK
920 W. LAKIE CANYON DR.
WINTER HAVEN FLA
 FIRE ARMS TYPE: NOT KNOWN GUN #: 359092
 & CONDITION: _____ CODE: OR-7-68
 PROCP: RED DISP.: 9 TEST: 55 CAL./CAL.: 3006
 READING: OK CHECKED BY: M. HARDY
 BREACH OPENING: OK APPROVED: GAH 10/22/81
 RECOIL SHOULDERS: OK APPROVED: AK 10/22/81
 FLANGE: OK APPROVED: P. H. 10/22/81
 TEST: _____ APPROVED: JWB 10/22-81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: MAH 10/22/81
BOLT RUSTY BRIGHT METAL ON BBL
MARS ON STOCK, 2 1/2 LB. TRIG PULL
 COMPLAINT: FIRED WHEN SAFETY IS RELEASED
 SUBJECT: _____
 COMMENTS: Unable to duplicate customer complaint.
Gun passes tick test, .002" vertical seal lift -
.017 Trigger connector engagement.
Trigger adjustment screws adjusted outside factory
as evidenced by red glue on these screws. Trigger pull
2 1/2# - Rem Specs 3# to 5#
Could get follow down by slamming bolt.