

Dec. 10, 1990

Remington Arms Inc
Arms Service Division
14 Hoeffler Ave.
Ilon N.Y. 13357

Attention: TARP Department

Please find enclosed my Remington 308, model 660, serial number 6209651. Just to give you a little history on the rifle, my brother purchased the gun new in Detroit Mich. about 1970. I have been the owner since 1974. Over the years the rifle had discharged about three time when the safety was released. I had always thought that maybe it was due to my error until last week. I had just returned to camp after a day of deer hunting, carefully released the safety when (BOOM) the rifle discharged and the bullet went into my pickup truck. (Did you ever see the damage a 308 can do to a pickup truck?). I can finally laugh about this and be thankful that I shot my truck and not one of my hunting partners. I understand from talking with Customer Service at Remington that this model 308 was recalled for the same problem that I am having. Please repair the rifle and return to me. Please take good care of my 308, its my favorite rifle, I taken 12 deer with it over the years.

Thank Your Very Much

Ralph G. Reynolds

Ralph G. Reynolds
Route #1 box 460
Ridgewood Hgts
Caryville Tenn. 37714