

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-16159INITIAL
FPS

CUSTOMER ORDER NO.

W/RUBBER BOOT

DATE RECEIVED
08/03/92DATE OPENED
08/12/92DATE CODE
LD 2-77SERIAL NUMBER
A6413960

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

ADL

ACCESSORIES

SCOPE BASE

HARD CASE

FROM:

ROGERS, ROY
8700 E. CO. RD. 85
MIDLAND, TX 79701

SHIP TO:

ROGERS, ROY
8700 E. CO. RD. 85
MIDLAND, TX 79701

CUST NO: 064753 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Left will malfunction as described above. However, Assembly of rifle showed trigger assembly has been improperly adjusted on the factory - such engagement is assumed and was checked in exam trigger pull - 5 lb; seen left 0006"

PARTS

COMMENTS

Rifle seen - inspection has been completed with outside factory, after new trigger assembly at E. Morsel Co. in getting of good will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTER

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1