

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN J STEKL

CUSTOMER ORDER NO.

RECEIVED 18/90	DATE OPENED 01/25/90	DATE CODE AW 3-72	SERIAL NUMBER 6536430	MODEL AND GRADE 700 243 BDL	ORDER R 90-03053
SSORIES W/STUDS					

M:

FRANK RUBIK
OLD RT 17
LIVINGSTON MANOR NY 12758

SHIP TO:

FRANK RUBIK
OLD RT 17
LIVINGSTON MANOR NY
12758

UNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
------------	--------------------	--------------------------------	------------	-----------	---------

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☒ MISUSED☐ MARRED

OWNER'S REQUEST

"It has developed a habit of firing when the safety is released and an attempt to fire, it doesn't fire, then when I go to reset the unfired casing it fires as the bolt starts upward".

able to duplicate complaint - Trigger pull 5 1/4 #, rear lift .0095". Disassembly with revealed bottom of action & trigger assembly very dirty & gritty - trigger assembly contaminated with dirt and excessive oil.

Per phone conversation with owner on 2/9/90 - clean present assembly, reset and return.

Charge \$10.00 for return postage

2/9/90
JDS.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88