

DATE : 2/16/90  
 TIME : 9:45  
 FILE # :  
 CALL IS TO/FROM CUSTOMER

*I am not sure if you need to set up a file.*  
 RECORD OF TELEPHONE CALL

CUSTOMER NAME: Larry Schenewerk DEALER: SCHENEWERK  
 ADDRESS: 115 Tedross Dr. ADDRESS:   
Calif. 916 65018  
 PHONE: 314-798-2147 W PHONE:

PRODUCT: 700 FFC CODE (S/N): 6486174  
 CALIBER: 30-06

10-15 yards from → NOT ON TARP

## CUSTOMER'S ATTITUDE:

BEGINNING:  IRATE  ANGRY X CALM  PLEASED  
 AT END:  IRATE  ANGRY X CALM  PLEASED

CUSTOMER CONCERN: Alleged follow down 3 or 4 times  
Only because of the structure.  
Looks like it will increase + 1st in  
chamber back before from safe to fire  
position + "gun back like trigger is back"  
 RESOLUTION: Works with + allegedly gun force  
when bolt handle is in process of closing  
Has been happening 2 years, allegedly.

COMMENTS: Customer stated he'd want a  
second opinion re: regulation of  
the trigger.