

RECEIVING AND ESTIMATING REPORT

BARBER - Kinzer PPS GAL RE0004393

INITIAL CUSTOMER ORDER NO		ATTN: JIM STEKL W/ 1 SPENT CASE	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
08/14/90	08/22/90	AG 3-B6	B6778672
MODEL AND GRADE		ORDER	
700 270 ADE		R 90-22374	

ACCESSORIES: W/STUDS

FROM:	SHIP TO:
SCHUEER, TOM 527 ELIZABETH ST WISCONSIN WI 54228	SCHUEER, TOM 527 ELIZABETH ST WISCONSIN WI 54228

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	FROM DATE	ESTIMATED	VIA
					V 422012332

REPAIR CHARGE	TAX	INSURANCE	TIPS	PARCEL POST	TOTAL

GUN CONDITION:

☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

1) shell head failed - expanded primer pocket - Remington factory load
2) rifle appears to have excessive headspace.

MAIN FAULT

Primer pocket of incident round expanded & dumped gas back into action.

PARTS

1) shell headspace of rifle & correct if necessary.
2) check foot for any damage to wood.
3) Test rifle after any repair.
4) Please expect to receive rifle by mail for September hunt.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

REV. 6/88