

REMINGTON ARMS REPAIR

AM SENDING MY DAUGHTERS REMINGTON MODLE 788 , 223 CALIBER
SERIAL NO. A6145826 FOR REPAIR. ON TWO SEPERATE HUNTING
THE FOLLOWING HAPPENED: A ROUND WAS CHAMBERED BUT THE
WOULD NOT GO ON. THE BOLT WAS THEN LIFTED UP BUT WAS NOT
BACK THEN THE BOLT WAS PUSHED BACK DOWN AND THEN THE
WOULD GO ON. WITH RIFLE UNLOADED I TESTED IT AGIN AND IT
SAME THING, AFTER GETTING IT TO GO ON SAFETY I PUSHED THE
BACK AND FOURTH A FEW TIMES AND WHEN PUSHING IT OFF SAFETY
NG PIN FIRED. I HOPE THE PROBLEM CAN BE FOUND AS THE RIFLE IS
CURATE, BUT I WOULD NOT LET ANYONE USE IT NOR WOULD I SELL IT
S PROBLEM.

THANKS

BILLY SCHULTE
RT. 5 BOX 330A
VICTORIA TEXAS, 77901

H/one 512-578-6124

Work 512-788-3255

*93 per phone with Mr. Schulte - rifle
used, had rifle stopped for refinishing*