

Remington
U.S.A.

REMINGTON NEW GUN REPAIR INVOICE

REMINGTON ARMS CO., INC.
BRIDGEPORT, CONN. 06607

Remington Recommended Gunsmith

Name Allison & Carey Gun Works
 Street 10218 S. E. Powell Blvd.
 City Portland State Ore Zip 97266

Customer's Name Kenneth Scott
 Street 533 Haussler Rd.
 City Kelso State Wa Zip 98626

Job # 25601

Date Firearm Received

9/12/79

Date Returned to Customer

6/20/80

Returned to Factory

Date

9/19/79

Via

UPS

Model

700

Cal. or Gauge

.243

Grade

Serial Number

A6537563

Complete Description of Customer's Complaint

Gun has fired when taken off safety. Customer was absolutely sure he did not
 have finger on the trigger.

Repairs Performed - Describe in detail

Sent to Remington Arms Service Section

Attn: Mr. Dennis Sanita

Received back from Remington UPS, after
 several letters and phone calls, 6/12/80/

Repair Charge Breakdown

Parts	\$	
Labor		20.00
Handling & packing		4.50
Test Ammunition		
Transportation		4.40
Total	\$	28.99

Approvals in order:

1. Field Representative

2. Regional Manager

3. Arms Service (2)

Date:

Date:

Date:

REV. 3/75

FIELD REPRESENTATIVE IN YOUR AREA