

P.I. 7-1 GUN EXAMINATION REPORT NUMBER: 173 MODEL: 100

GENERAL CONDITION: F+1P R #: 2110

INSIDE WORK: RECOIL SPRING STAY DATE: 11-20-70

STOOD A 750 - Hook refinished outside FROM: 5/4/75

FIRE AMMO TYPE: NOT KNOWN Remington 2801-5-37

& CONDITION: 73633

PROOF: REP INSP.: N TEST: 114 CODE: 13 0-1-67

HEADING: OK GA./CAL.: 305

BRECH OPENING: OK CHECKED BY: N-1-1-70

RECOIL SHOULDERS: OK APPROVED: 9/24 12/21/

CHAMBER: OK APPROVED: 12/21/70

TEST: OK APPROVED: R.B. 12-2

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 12/21/70

B.R. 12 - METAL CH. REC. 1 1/2

1 - "TRIGGER" COIL AND ALL

4 1/2 LB TRIC PULL

COMPLAINT: FIRE WHEN COILS DIVS

INCIDENT:

COMMENTS: Passed Trick test. Trigger Pull 4 1/2 #

Gun involved in recall program.

N/39

Recall for control under recall program