

- 2 -

Kent F. Hudson, Esq.
Purvis, MS 39475


February 06, 1986

Based on our findings, Remington Arms Company, Inc., cannot assume any liability or responsibility for this unfortunate incident that was created from a condition beyond our control.

Please advise your client that it is most important for us to readjust the trigger back to factory specifications to restore it to a safe condition.

Thank you for your cooperation on allowing us to examine the exhibits and we will await your reply.

Sincerely,



E. F. Sienkiewicz, Manager
Product Service

EFS/cal