

From: Walter Smith

2-6-94

TO: Remington Arms Company Service Division

Attached is my Remington Model 700 bolt action .243 Winchester rifle Serial #6649099 that needs repaired. The last time I used the rifle hunting when I pulled the trigger the gun did not fire and when I tried to eject the bullet by lifting the bolt the gun fired.

(With no shell in the chamber) With the safety on the fire position if you open the chamber and and then slide the bolt to the closed position, when you push the bolt down the gun automatically fires. I have tried taking the bolt out of the gun and putting it back in to see if it made any difference but it did not. Please call me and let me know what needs to be done in order to repair this gun. Thankyou. Walter Smith

Address: (Return) Work Phone # 1-615-3742-007
3209 LuAnn Drive Home Phone # 1-615-399-082
Antioch, TN 37013