

P.I. YES GUN EXAMINATION REPORT NUMBER: 215GENERAL CONDITION: FAIROUTSIDE WORK: SCOPE SCREW REMOVEDFIRED AMMO TYPE: NOT KNOWN

& CONDITION: _____

PRCOF: (PEP) INSP.: 130 TEST: 57HEADING: OKBREACH OPENING: OKRECOIL SHOULDERS: OKCHAMBER: OK

TEST: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

SLIGHT MARKS IN WOODMETAL BRIGHT ON RBL. FLOOR PLATEAND B-LT.COMPLAINT: ACCIDENTALLY DISCHARGED TWICE

INCIDENT: _____

COMMENTS: {

Snlt stop release would not work.- Trigger control extremely full of oil & crud.- Trigger pull 7 3/4# - Passed twist test.- Trigger adjusting screw head damaged - appears to have been adjusted out side of factory and reversed.MODEL: 700 RBLR #: 00626DATE: 1-3-80FROM: FAYOY STAVELANDFIS3
COLONIA - FLAGUN #: A1271784CODE: AI-3-76GA./CAL.: 3006CHECKED BY: LI-44804APPROVED: SN 3/25/80APPROVED: JL 3/25/80APPROVED: R.B. 3-25-80APPROVED: VED 3-25-80
200 = 2150