

INITIAL

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ACCESSORIES

SCOPE BASE

FROM:

T.V.'S RELOADING SHOP
119 MAXEY ROAD
HOUSTON TX 77013
USA

SHIP TO:

T.V.'S RELOADING SHOP
119 MAXEY ROAD
HOUSTON TX 77013
USA

CUST NO: 022477 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

GUN CONDITION

☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☒ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Rifle cannot be made to malfunction, however, inside of trigger assembly is contaminated with a greasy substance that is affecting movement of trigger. The same material appears to be on the bolt stop causing sluggish movement.*

Trigger pull - 3 3/4 pounds, near - 0.12"

PARTS

COMMENTS

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE