

INITIAL FPS	CUSTOMER ORDER NO.		ATTN: FRED MARTIN		
DATE RECEIVED 05/03/94	DATE OPENED 05/04/94	DATE CODE LQ 2-78	SERIAL NUMBER A6570501	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MM MAG BDL
ACCESSORIES W/STUDS					

FROM:	SHIP TO:
TRI-STATE PLANT FOOD, INC. HAROLD GRIFFIN 1615 E. BURDESHAW ST. DOTHAN AL 36303	TRI-STATE PLANT FOOD, INC. HAROLD GRIFFIN 1615 E. BURDESHAW ST. DOTHAN AL 36303

CUST NO: 096881 G.L.O.B.

ACCOUNT NUMBER	ACCOUNT NUMBER W/C 039015	WRITE ☐	FROM DATE	ESTIMATED	VIA UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: *My 1978 Unable to duplicate customer concern. Examination reveals that the bolt stop valve would not retract. Trigger pull measured at 2 1/2 lbs. all trigger adjustment screws have been re-set. During disassembly with customer on 5/1/94, he stated he has never adjusted the trigger weight and that rifle was purchased new.*

PARTS: *#20345*

COMMENTS: *Applied study via picture of good unit to check action & trigger components. Trigger assembly. Explained that normally there is a special trigger but when we find the above condition. Go ahead.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/9