

RECEIVING AND ESTIMATING REPORT

COMMENTS

TIAL CUSTOMER ORDER NO.

PS A11553

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

3/10/91

05/13/91

AQ 3-78

A6572255

700 7MM MAG

BDL

R

91-10713

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

OM:

TROP GUN SHOP
709 CLOVERLEAF ROAD
ELIZABETHTOWN

PA 17022

SHIP TO:

TROP GUN SHOP
709 CLOVERLEAF ROAD
ELIZABETHTOWNPA
17022

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

AIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

IN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

Fires when closing batt.

IN FAULT

Cannot duplicate complaint. However, trigger assembly has been completely mis-adjusted outside factory as evidenced by foreign sealant on adjustment screws - 1) non-engagement is extremely excessive 2) over travel is excessive. Firing pin spring is rusted & heavily oiled. It has been tampered with and improperly maintained. Safe lift .008", trigger pull 3 1/2 pounds.

Send quote for new trigger assembly at 1/2 original cost as gesture of good will.

Note: sender claims rifle is less than a year old, however, it was produced in March of 1978!!

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/90