

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER R 94-15275	
INITIAL FPS CUSTOMER ORDER NO.							
DATE RECEIVED 05/09/94	DATE OPENED 05/09/94	DATE CODE AC 3-82	SERIAL NUMBER A6584722	NEW SERIAL NUMBER	MODEL AND GRADE 700 22-250	CLASSIC	
ACCESSORIES W/STUDS L/SIGHTS							
FROM: TROXELL, DAVID E. RR 1 BOX 215A LIBERTY PA 16930				SHIP TO: TROXELL, DAVID E. RR 1 BOX 215A LIBERTY PA 16930			
CUST NO: 097077 C.D.O.							
ACCOUNT NUMBER		ACCOUNT NUMBER W/C		WRITE ☐	FROM DATE	ESTIMATED	VIA V500716755
GUN CONDITION				REPAIR CHARGE 20.00			
☐ NEW ☒ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED				EXCISE TAX INSURANCE UPS PARCEL POST TOTAL			
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1	<i>"Wood had some of safety in taking off it then"</i>				
TRIGGER GROUP		B2					
BOLT ASSY.		B3					
BARREL ASSY.		B4					
REC. ASSY.		B5					
WOOD			C1	D1	E1	F1	
METAL			C2	D2	E2	F2	
MAIN FAULT <i>With Mfg 1982 upon receipt it was inoperative. I found down under trigger. Adjustment would not be trigger adjustment screw and screw adjustment screw have been re-set. Screw removed from both screws. Lot of safety inspection. Gun was not delivered in action.</i>							
PARTS				COMMENTS <i>Upon receipt trigger was set and when set at 1/2 normal test, no a good test good unit.</i> <i>Go ahead</i>			
REPAIRMAN				PROOF	CLEAN ☒	TEST ☒	TARGET
GALLERY TESTER				DATE	DATE	DATE	DATE
OFFICE COPY				R06025 REV. 1/04			