

RECEIVING AND ESTIMATING REPORT							
INITIALS		CUSTOMER ORDER NO.		DATE RECEIVED		DATE OPENED	
DATE RECEIVED		DATE OPENED		DATE CODE		SERIAL NUMBER	
8-21-78		8-21-78		W1-8-78		1766	
ACCESSORIES		TOOLS		SCOPE		ORDER	
						R	
FROM: DALE TRUE LEROY KS 66856				SHIP TO: DALE TRUE LEROY KS 66856			
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		PROM. DATE		ESTIMATED PRICE	
						UPSD	
REPAIR CHARGE		TAX		INSURANCE		UPS	
PARCEL POST		TOTAL					
GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ MARRED							
CUSTOMER'S REQUEST							
<i>"The rifle fires when you release the safety with the barrel pointing down"</i>							
MAIN FAULT							
<i>Connector is broken from pierced primers - Remington factory ammo being used.</i>							
PARTS				<i>1) replace trigger assy. at No-charge</i> <i>2) Check firing pin/ole in bolt face - replace bolt at No-charge, if necessary.</i> <i>3) Complete repairs and return, do not charge \$10.00 handling or return postage</i> <i>2/22/90</i> <i>JH.</i>			
REPAIRMAN		PROOF		CLEAN		TEST	
GALLERY TESTER		DATE		DATE		DATE	

RD6925 REV. 6/88