



RD 5398 REV. 10/84

BARBER - Kinzer PPS GAL RE0005205
REMINGTON ARMS COMPANY, INC.SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS
ILION, NEW YORK 13357

PAGE 1

DATE: 02/26/92

PARTS: (315) 895-7493, REPAIRS: (315) 895-7791

GROUND SAVER

SOLD TO CUSTOMER NUMBER: 56975
REPAIR ORDER NO.: 92-03184
VARVERA, SALVATORE
13935 DAVEY
FLORISSANT MO 63034

SHIPPED TO REPAIR ORDER NO
JHU JEN 92-03184
VARVERA, SALVATORE
13935 DAVEY
FLORISSANT MO 63034

THIS IS AN ESTIMATE TO REPAIR, RECONDITION OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW. RETURN THE FIRST COPY TO REMINGTON ARMS CO. INC. ILION, NY 13357. KEEP THE SECOND COPY AS YOUR RECEIPT.

REPAIR TO TAKE ABOUT 3 WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN THIRTY DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED.

722 300 SAV
W/STUDD

CONTENT AND SERIAL NUMBER: 170782

CUSTOMER REQUEST:
FIRES ON CLOSING -

MAIN FAULT FOUND:

FIND NO FAULT - CANNOT DUPLICATE COMPLAINT - RIFLE & TRIG
ASSEMBLY OPERATE PROPERLY IN EVERY RESPECT -
DATE OF MFG: 03-51

1 0826345 TRIGGER ASSEMBLY
OFFER TO RETURN RIFLE AS IS OR OFFER TO REPLACE TRIG ASSM
AT 1/2 NORMAL COST, AS A GESTURE OF GOOD WILL - IF THAT
WILL BETTER RESTORE CONFIDENCE IN THE RIFLE.
REPAIR CHARGE -
NOTE: THIS RIFLE IS 41 YRS. OLD & HAS APPARENTLY OPERATED
PROPERLY FOR A LONG TIME.
EZ/HAR

TOTAL REPAIR CHARGE
TAXES

INSURANCE
PARCEL POST

TOTAL
CHARGES

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

CUSTOMER COPY

BARBER - Kinzer PPS GAL RE0005205

PPS 05200