

GUN# B29 w/ SCOPE
SERIAL # 71001313
CAL- 30.06 SPRG.

REMINGTON M/710 DAT PHASE II
DAILY TEST DATA SHEET

TRACKING # TLW0010
PROJECT #241095

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-	
				RDS. FIRED	TOTAL RDS.
JW/ SW	9/9/00	HEADSPACE	MIN. +.001		
JW/ SW	9/9/00	PROOF, HEADSPACE	PROOF, INSPECT, HEADSPACE MIN. +.002 + PROOF STAMP	1	1
JA/BL/JC	9/9/00	Trigger Pulls			
JA/BL/JC	9/9/00	Sear/Trigger Engagement T/Sear LIFT			
JC	9/9/00	Inspection			
JW/SW	9-10-00	SAAMI DROP TEST	JAR OFF, DROP, ROTATION - BOLT HANDLE BROKE ON SAAMI DROP TEST, BARREL HORIZONTAL, LEFT SIDE OF STOCK UP. REPLACE BOLT W/ BOLT OUT OF GUN # 71001307 THAT HAD ALREADY BEEN PROOFED, HEADSPACE MIN. +.002		
JA/BL/SW	9-11-00	Trigger Pull/Engagement	After S.A.A.M.I. Drop (See TLW0010 AR)		
JA/BL/SW	9-11-00	Inspection	No cracks		
MART	9-11-00	MAGNAFLUX BOLT HEAD	- NO INDICATIONS		
JW/ SW	9-13-00	EXTENDED JAR OFF	6"-18"-24"-48", FRONT TWO SCOPE RAIL SCREWS BROKE OFF AFTER INSPECTION ON 24" DROPS - PKR tapped out - Replaced - Continued with 48" Drop		
JW/ SW	9-14-00	TRIGGER PULL/ENGAGEMENT	AFTER EXTENDED JAR OFF		
SW	9-17-00	Engagement	After Extended Jar off engagement was .0192 reset to .0235		
JW/ SW	9-15-00	EXTENDED DROP TEST	MAGAZINE WELD BROKE ON 72" EXTENDED DROP TEST ON BARREL HORIZONTAL, RIGHT SIDE UP - REPLACED MAGAZINE		
JW/ SW	9-15-00	EXTENDED DROP TEST	PLASTIC INSERT BROKE ON BARREL HORIZONTAL BOTTOM OF STOCK UP		
JW/ SW	9-28-00		REPLACED PLASTIC INSERT		
JW/ SW	9-28-00		SET TRIGGER PULL + ENGAGEMENT AFTER REPLACE INSERT		
JW/ SW	9-28-00	EXTENDED DROP TEST	CONTINUED TEST - @ 72" - COMPLETE		
JW/ SW	9-28-00	Inspection	Scope bent, Bolt Handle bent. Engagement Low .0144		
JW/ SW	9-29-00		Reset Engagement .0210/Retink. Trigger Pull		
JW/ SW	9-29-00	Extended Rotation Test	Complete		
JA/BL	10-2-00	Trigger Pull	3.33 average		
JA/BL	10-2-00	Engagement	.0139		

THIS SHEET IS TO ACCOMPANY THE FIREARM AT ALL TIMES THROUGHOUT TESTING

Forms

ET18878