December 11, 1980

-2-

Even though we could not find anything wrong with the rifle or present trigger assembly, we are replacing the trigger assembly, at no-charge, under the terms of our recall, to insure that Mr. Simmons' faith in the rifle is rectored.

Thank you for having afforded us this opportunity to examine the rifle and to be of service.

Sincerely,

J.A. Stakl, Supervisor Pirearms Product Service

JAS: tpp

BARBER - Kinzer PPS GAL RE0005481