

RECEIVING AND ESTIMATING REPORT

COMMENTS

BARBER - Kinzer PPS GAL RE0005484

ORDER
R 92-07318

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 03/04/92	DATE OPENED 03/12/92	DATE CODE CK 4-90	SERIAL NUMBER C6519588	NEW SERIAL NUMBER	MODEL AND GRADE 700 17REM	BDL
ACCESSORIES		W/STUDS		SCOPE BASE		L/SIGHTS

FROM:

SHIP TO:

WILDERNESS SPORTS II
331 RIVER RD
P O BOX 246
WILLINGTON CT 06279

WILDERNESS SPORTS II
331 RIVER RD
P O BOX 246
WILLINGTON CT 06279

CUST NO: 040659 C.J.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

- GUN CONDITION
- ☐ NEW
 - ☐ LIGHTLY WORN
 - ☐ WORN
 - ☐ VERY WORN
 - ☐ UNREPAIRABLE

REPAIR CHARGE
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	Fired when closing bolt				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Rifle inoperable as received. Trigger assembly has been improperly adjusted, outside factory - original trigger gone from adjusting screws. It is insufficient gun engagement as insufficient over-travel - rifle will not cock upon closing bolt.

PARTS

COMMENTS

Quote for new trigger assembly at normal cost, as function of gun is
Note: Warn against trigger adjustments outside of factory by individuals

REPAIRMAN HJB	PROOF	CLEAN	TEST	TARGET	PATTER
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 81

BARBER - Kinzer PPS GAL RE0005484

PPS 05479