

Henry D. Williams
216 Conellin
Lubbock, Texas
77501

Dear Sirs:

I am the original owner of this
44-700 Bar 30-06 rifle and have taken
good care of it. Several misfiring incidents
however have prompted this letter and
return of the firearm. Even though the
rifle is 10 or 11 years old, only 35 or
50 rounds have been fired through it.
Of these 35 rounds, four have been
fired without pulling the trigger. The
first incident was when I was loading
purchased the gun and was loading
it. The gun discharged while pulling
a live round into the chamber with the
bolt. I took it immediately to a gunsmith
who gave it a brief inspection and told
me nothing was wrong with it.
The second and third incidents occurred
last year while sighting in the scope.
One round discharged as before and another
round discharged as I checked the
safety off. Having down near broken parts
and fingers on three separate occasions I
put the gun away until this season. The
fourth incident occurred yesterday when
I was using the rifle after hunting.
The gun fired while taking the safety