

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: GOOD R # : 27601
OUTSIDE WORK: SCOPES MOUNTED DATE: 10-26-72
FROM: INDIAN ROCK
FIRED AMMO TYPE: — PERZENT
& CONDITION: _____ GUN # : 27601-1
PROOF: R.E.P. INSP.: 11 TEST: 55 CODE: CP-4/1
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: — APPROVED: _____
CHAMBER: — APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DEFORMED COMPONENTS.

COMPLAINT: GUN FIRES WHEN BOLT IS CLOSED.

INCIDENT: FOLLOWS DOWN

COMMENTS: THE SEAR-CONNECTOR ENGAGEMENT WAS
SET TOO CLOSE BY FINAL ASSEMBLY.