

March 19, 1985

Remington Arms Co.

Dear Sirs :

I have been informed that I have a Remington XP100 -.221 cal. that may be included in a factory recall for its' trigger / safety.

The serial number is 5439 and the safety is the type that has to be released before the bolt can be opened. I have also noticed that the "sear safety cam" is of two piece construction. The one in my 7mm XP100 is one piece.

I have had my XP100 rebarreled to a longer .221 cal. barrel, but no work has been done to the trigger assy. or any other metal parts.

If my XP100 is subject to your recall could you provide me with the following information :