

Remington Arms Co., Inc.
Product Service
Legal Case #:1922

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
138898	12/28/2007	1/3/2008	1/3/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Charles	Adams	161 Covell Rd	Granville	MA	01034		H 413-258-0285

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C	fired on bolt closing			

1/7/08-correspondence from repair-bolt closes hard and sometimes goes off on bolt closing.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl	DOM
Remington	CF/BA	700/7MM REM MA	20000	6587551 WW	8/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner		
	PARKER DIST NEW ROCHELLE N Y	TWO PIECE SCOPE BASE,BOTTOM HALF OF RINGS	N		

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA under SMP						
	Repair/Replacement Cost	Repair/Replacement Date				

1/7/08-quote sent to replace TA under smp.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/3/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	TRIGGER DIRTY
Barrel	Description		24" 7MM REM MAG
	Date Code		WW
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Abused; Functioning	OUT OF POSITION
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.005
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE,BOTTOM HALF OF RINGS

ww 8/72
4#
24"
.005

Dear Sir,

1922

This rifle was given to me
from my father's store when he died
I really don't know any of the
history of it

The problem is that the bolt
doesn't really head, find at times
when it closes it goes off. The only
ammo I use is Remington ammo
so reloads

My phone is - 1-413-258-0285

Thank you

Charles Craig Adams

CHARLES ADAMS
161 COVELL RD
GRANVILLE MA 01034

10 LBS
RS

1 OF 1

SHIP TO:

ATTN: ARMS SERVICES
REMINGTON ARMS CO, INC
14 HOFER AVE
ILION NY 13357

Serial Number: 6587551

Model: 700



RE00138898

Could not duplicate concern.
TRIG. ASSM Dirty. EXT. out of
position. Replace TPA under
BOLT LOCK program. Ron
\$ 20.00. + SEND Quote
to replace EXTRACTOR.