

Remington Arms Co., Inc.

Product Service

Legal Case #:2460

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
146240	6/10/2008	6/11/2008	6/11/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Cimino's Gun & Archery	Cimino's		N306 Tree Ln	Merrill	WI	54452		W 715-536-1021

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	rifle fired on its own	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

6/13/08-correspondence from repair-dealer opened the rifle case. Without touching the bolt or trigger, the rifle fired when they picked it up. lw 6/13/08-Ed spoke to customer, rifle had been sitting in case under bed for over 10 years.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN		C6306264	EI	10/13/1988
Date Purchased	Where Purchased	Accessories	Original Owner			
	MATHEWS & BOUCHER	TWO PIECE SCOPE BASE	U			

CONCERN:WENT OFF BEFORE TOUCHING BOLT

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repair at discount						
	Repair/Replacement Cost	Repair/Replacement Date				

6/13/08-Quote sent to repair at discount.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/11/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	SPENT CASE RETURNED
Barrel	Description		22" 270 WIN
	Date Code		EI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2460&Type=Case>

6/13/2008

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE



BARBER - Kinzer PPS GAL RE0008654

GUN & ARCHERY, INC.

N306 TREE LANE . P.O. BOX 855 . MERRILL, WI 54452

715-536-1021 Fax 715-536-4040

All Sales Final. Lay-A-Ways Due In 90 Days. No Cash Refunds On Lay-A-Ways.

No Warranty On Military Firearms. No Refunds Or Exchanges On Special Orders, Firearms, Ammo Or Scopes.

10% Stocking Fee On Cancelled Lay-A-Way Items.

If You Leave A Loaded Firearm Within The Reach Or Easy Access Of A Child, You May Be Fined Or Imprisoned Or Both If The Child Improperly Discharges, Possesses Or Exhibits The Firearm.

2460



22"
ET 10/88
5#

Customer's Order No.		Date		May 31 08 ²⁰	
Name Remington Arm Service					
Address ATTN: Service Dept. 14 Hoeffler Ave					
Elion, NY 13357				Phone:	
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MOSE. RETD.
					PAID OUT
					LAYAWAY
QUAN.	DESCRIPTION			PRICE	AMOUNT
	Remington 700				
	270001. # C6306264				
Please look over -					
I had talk to Ed ext. 8788					
May 16 08 - customer had come into					
are store I (Deb) open up the rifle case and					
was going to open bolt. But before I could					
touch bolt rifle went off. my other hand was					
nowhere near trigger. Rifle just went off.					
Is there any way of telling why rifle went					
off?? I am sending empty casing					
any question please let me know					
PH# 715 536-1021					
Thank you!					
All claims and returned goods MUST be accompanied by this bill.					TAX
Received By Deb					TOTAL

could not duplicate concern
up here + PA, check over,
clean + function test.
AT 1/2 normal charge.
Quote

Number: C6306264

Model: 700



RE00146240

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00146240** Serial: **D6306264** Model: **700 LH Center Fire** Repairman: **New 6/10/2008 6:10:27 AM**
 Verify Repair Caliber: **270 WIN** Produced: **10/13/1988** Status:

Address Information

Customer: **CIMINO'S GUN ARCHERY** Received From: **CIMINO'S GUN ARCHERY**
 Name: **CIMINO'S GUN ARCHERY** Return To: **CIMINO'S GUN ARCHERY**
 Address 1: **N306 TREE LN** Address 2: **N306 TREE LN** PO Box:
 City: **MERRILL** City: **MERRILL**
 State: **WI** Zip Code: **54452** Country: **US** State: **WI** Zip Code: **54452** Country: **US**

History / Status

Date	Code	User ID	Desc1	Desc2
6/10/2008 6:10:2	New	valentids	Repair Added	
6/11/2008 7:44:0	Expedite	pencerl	From Check In	To: Repair Bench

Shipping / Billing

Current Status: **New**
 6/10/2008 6:10:27 AM
 valentids
 Repair Bench
 Repair Location: **ILN**
 Current Location: **ILN**
 Transfer Number:

Repair Search **Refresh** **Close**

supryll 6/11/2008 10:07 AM C4FS NUM INS SCRL

start Unbox: Microsoft Out... Microsoft Excel PPS H... Arms Services Repair... closed cases: Micro... CLOSE

The rifle may have moved forward and the trigger ~~was~~ activated by material inside the case. We could not get the rifle to fire without pulling the trigger.

FRED