

Remington Arms Co., Inc.
Product Service
Legal Case #:1909

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
138809	12/28/2007	1/2/2008	1/2/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Dunn's Sporting Goods	Dunn's		8733 Commercial Blvd	Pevely	MO	63070		W 636-475-4240

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	Concern:1007 Fired on Safe Release		Unknown	
C	fires when safety is turned to fire			

1/7/08-correspondence from repair-fires when safety is turned to fire on occasion.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN		6809147	RY	11/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA under SMP						
Repair/Replacement Cost	Repair/Replacement Date					

1/7/07-quote sent to replace TA under SMP.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/2/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		RY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

BARBER - Kinzer PPS GAL RE0008684

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	NO NUMBER ON BOLT BODY
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

REPAIR
TAG

145890

DUNN'S SPORTING GOODS, INC.

8733 Commercial Blvd.
PEVELY, MO 63070
(636) 475-6240

RECEIVED BY	CUSTOMER		COPY NO.	K 145890
	Charles Moody			
Thank You! CASH ON COMPLETION OF WORK	ADDRESS		MODEL OR SERIAL NO.	TROUBLE REPORTED
	700 West 6809147			
TOTAL	DESCRIPTION OF MATERIAL USED		DATE RECEIVED	PROCESSED DELIVERED
	P-145			
TOTAL	AMOUNT			
MATERIALS				
LABOR				
TAX				
TOTAL				

Serial Number:

6809147

Model: 700



RE00138809

could not duplicate concern
TRIG. ASSM set screws altered.
Replace TPA, check over, clean
under BOLT lock program for
\$ 20.00 + 24H Quote

1909

24 11/74
2.5#
22"
.009