Remington Arms Co., Inc. Product Service Legal Case #:2929

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 155305 12/2/2008 12/3/2008 12/3/2008

Customer Information

TypeBusinessFirst NameLast NameStreetCityStateZipAgeContactReporterGander MountainGander Mountain2890 Acquest Ave SEKentwoodMI49512W 616-975-1000

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause: 4038 Could Not Duplicate Concern

Unknown

S Fires by itself Concern:1025 Unexplained Discharge - No Mention of Safety Position

С

Customer says the firearm will go off by itself.

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/7MM REM MA
 25803
 B6467103
 PD 6/1/1983

Date Purchased Where Purchased Accessories Original Owner

Original Owner

MATHEWS & BOUCHER ROCHESTER NY TWO PIECE SCOPE BASE

U

CONCERN: WILL GO OFF BY ITSELF

Ammunition Information - None Defined
Other Products Information - None Defined
Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date

Settlement APV APV

repair at no charge, goodwill

Repair/Replacement
Cost
Bate
65.00
Repair/Replacement
Date
12/3/2008

12/3/2008 could not duplicate customer's concern. Returned to AS to install a new TA at n/c as a gesture of goodwill to restore customer's confidence in the rifle fis.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/3/2008
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	GANDER MTN STATED THAT CUST WAS USING 3006 CAL AMMO IN RIFLE
	Description 24" 7MM REM MAG Date Code PD	24" 7MM REM MAG	
		PD	
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		

ì			٦
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False]
	Block Condition	Select	
Locking	g Lug Condition Slightly Worn; Functioning		
	Notch Condition	Select	
	Exterior Condition	Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	1;
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Like new; Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Functioning	
	Pull	Select	4.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	1 .
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Repair Inquiry	
Repair Number RE00155305 Verify Repair	Senal: 86467103 Model 700 Center Fire: Caliber: Repairment Robert Firek. 7 MM-REM:MAG Produced: 06/23/1983 Status: Estimating 12/2/2008 8:34:05 AM
Name: GANDER MOUNTAIN Address 1: ATTN CINDY KILBRIDE	GReceived From Return To CReceived From GANDER MOUNTAIN 2890 ACQUEST AVE SE
Address 2 180 E 5TH ST SUITE 1300 City SAINT PAUL State MN Zip Code 55101	PO Box PO Box
Date Code 1 11/15/2008/5:14: New 11/15/2008/5:17: Update 12/17/2008/11:17: Expedite 12/27/2008/8:34:1 Estimate	Shipping / Billing Shipping / Billing Shipping / Billing
Repair <u>S</u> earch	Refresh Close
supryfl 12/3.	2008 9:27-AM CAES NUM INS ISCRIC

Installing new TPA as gestore of goodwill. Could not deplicate customer's concern.



Service Request

201/83 21/4 4.5#

SHIPPED TO VENDOR/STORE:

REMINGTON ARMS CO. INC. ARMS SERVICE DIVISION 14 HOEFLER AVE.

ILLION, NY 13357

Attn: WARRANTY REPAIR

Date Shipped: 11/07/2008

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 4-38-081-01-7b-02241

Service Order # 5200

Attn: Gun Parts Dept. 2890 Acquest Ave SE Kentwood, MI 49512

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

700

Type:

Rifle

Serial Number: B6467103

Cased?:

`Model:

700

Cal/Ga.: 7MMRM

DESCRIPTION OF ITEM RETURNED:

REMINGTON MODEL 700 7MM SERIAL # B6467103

REASON FOR RETURN:

could not duplicate concernot goes off by itself. Check over, hippin, ADJUST AS Needed. Hip bece TPA TO JUSTORE CONFIDENCE in TIPLE AT N/C FOR TPA DNLY.

CUSTOMER CLAIMS TO HAVE CALLED REMINGTON FOR WARRANTY REPAIR ON TRIGGER CUSTOMER CLAIMS THE FIREARM WILL GO OFF BY ITSELF HAVE DISCOVERED HE WAS SHOOTING 3006 AMMO

PLEASE EVALUATE FOR SAFETY ISSUES

ATTENTION VENDOR

Please contact me with any questions or concerns.

Bonnie Comella (616) 975-1000

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

GANDER MOUNTAIN COMPAN

ATTN: CINDY KILRIDE

180 E. Fifth Street Suite 1300

St. Paul, MN 55101

B6467103

Model: フ@@



RF00155305
BARBER - Kinzer PPS GAL RE0008737