

Remington Arms Co., Inc.  
Product Service  
Legal Case #:2947

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
156472	12/6/2008	12/8/2008	12/8/2008				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Mobile Shooting Center		Mobile Shooting	9170-C Airport Blvd	Mobile	AL	36608		W 251-633-8629

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	fired on safe release Concern:1007 Fired on Safe Release			
C				

Customer says, This gun fires when safety is released, It had had 2 misfires due to this issue. Please repair and return fls.

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	A6477367	OO	7/7/1965
Date Purchased	Where Purchased	Accessories	Original Owner			
	J C PENNY TUCKER GAREPAIRS0	SOFT CASE,SLING	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement Cash Settlement Reim. Date APV Cash Date APV
BLM Program			

Repair/Replacement Cost Repair/Replacement Date

45.00 12/11/2008

12/8/2008 Returned to AS for bolt lock modification program. Install new TA and clean action quote \$20 plus shipping and handling fls.

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/8/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		OO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	

	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.009
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SOFT CASE,SLING

Arms Services Repair & Estimate System

File: Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

**Repair Inquiry**

Repair Number: **RE00156472** Serial: A6477367 Model: 700 Center Fire Caliber: 3006 SPRG Produced: 07/07/1965 Repairman: **Bruce Travis**  
 Verify Repair Status: **ApprovalHold 12/8/2008 8:20:52 AM**

**Address Information**

Customer: ☒ Received From Return To: ☐ Received From

Name: **MOBILE SHOOTING CENTER** **MOBILE SHOOTING CENTER**

Address 1: **9170 C AIRPORT BLVD** **9170 C AIRPORT BLVD**  
 Address 2: **PO Box** **PO Box**

City: **MOBILE** **MOBILE**  
 State: **AL** Zip Code: **36608** Country: **US** State: **AL** Zip Code: **36608** Country: **US**

FFL: ☐ ☐ ☐ ☐ ☐ ☐

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	User ID	Desc1	Desc2	Current Status
12/6/2008 6:25:1	valentids	Repair Added		ApprovalHold
12/6/2008 6:27:1	valentids	Repair information change		12/8/2008 8:20:52 AM
12/6/2008 6:29:4	valentids	From: Check In	To:	Travisbw
12/8/2008 8:20:5	Travisbw	Estimate Update	Status: ApprovalHold	ApproveRack
12/8/2008 10:30:	pencertl	From: Product Services	To: ApproveRack	Repair Location
				ILN
				Current Location
				ILN
				Transfer Number

Shipping Hold ☐ Interface Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return As Received ☐ Has been Approved ☐ Internal Repair ☐

Repair Search Refresh Close

suprtyl 12/8/2008 10:30 AM CAPS NUM INS SCRL

start Inbox - Microsoft Out... Arms Services Repair Microsoft Excel - PS H... Current Cases - Micro... 10:30 AM

Returned to AS for Bolt lock  
 - modification program. Installing new  
 TA & cleaning action.

FLS

RECEIVED  
 DEC 09 2008  
 BY: .....

**MOBILE SHOOTING CENTER**

9170-C Airport Blvd.  
MOBILE, AL 36608  
(251) 633-8629

CUSTOMER'S ORDER NO.		PHONE		DATE	
				11-24-08	
NAME <i>Remington 700</i>					
ADDRESS <i>30-06</i>					
SERIAL # <i>A6477367</i>					
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	PAID OUT
QTY.		DESCRIPTION		PRICE	AMOUNT
		<i>Please repair or replace. This gun fires when safety is released. It has had 2 misfires due to this issue. Please repair and return to</i>			
		<i>Thanks,</i> <i>A. Bird</i>			
RECEIVED BY				TAX	
				TOTAL	

C PRODUCT 610

All claims and returned goods must be accompanied by this bill.

*Thank You*

Serial  
Number:

A6477367

Model: 700



RE00156472

could not duplicate concern  
RPM TPA check over, can  
under both loan programs  
Loan \$20.00 + S&H.