

Remington Arms Co., Inc.
Product Service
Legal Case #:2243

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
143141	3/14/2008	3/17/2008	3/17/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Greg	Stone-employee	870 Remington Dr. PO Box 700	Madison	NC	27025		W 336-548-8642

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	fires on safe release	Cause:4006 Concern:1007	Altered Adjustments or Components Fired on Safe Release	Unknown
C				

3/20/08-correspondence from repair-gun fires when moving safety.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	700/6MM REM	20000	6537136 AW	3/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner		
	MATHEWS&BOUCHER ROCHESTER N Y	TWO PIECE SCOPE BASE	U		

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA						
	Repair/Replacement Cost	Repair/Replacement Date				
	35	3/20/2008				

3/20/08-tpa replaced.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		3/17/2008

Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	WILL FOLLOW DOWN
Barrel	Description		24" 6MM REM HB
	Date Code		AW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Worn; Functioning	DAMAGE FROM LEAKING PRIMERS
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	SEARCAM STICK Y/BINDING
	Pull	---Select---	2#
	Altered	True	SET SCREWS ALTERED NO TRIG RETURN
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Remington®

2243

2#
AW 3/7
24"
005

Product Service
Attn: Fred Supry

Ref: Model 700 6mm, Serial number 6537136

Gun fires when moving safety

Please evaluate firearm and install new trigger.

Any questions, please contact John Loschin.

Greg Stone
Madison employee - x8642

Trig. set screws altered, no
trig. return. Sear cam sticky
binding. Replace TPA, check over
clean under bolt lock safety
Low \$ 20.00

Quote.

Serial
Number:

6537136

Model: 700



RE00143141