Remington Arms Co., Inc. Product Service Legal Case #:4844

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 10/26/2010 11/4/2010

209053 11/3/2010

Last Name Street City Contact Type Business First Name State Zip Age Incident Forest Roberts Jr 3616 N. Calhoun Hwy Grantsville 26147 H 304-354-7519

Incident Information

FSR

Customer Information

Claims Codes Repair Est. Medical Treatment **Medical Status**

ΡI

PD Could Not Duplicate Concern Cause:4038

Unknown Concern:1007 Fired on Safe Release

S C

10/26/10 Per call from Roberts, he has a Model 7 that he had a FSR with after he bought it new. He applied WD40 in the trigger and blew it out with low pressure air to clean. He says he has not had a problem since but saw the CNBC and wants to get it checked.cm

Firearm Information

Mfg. Model/Ga. SKU Bbl. DOM Type Serial

Remington CF/BA 7/243 WIN 24739 S7646920 KW 5/2/2002 11:00:47 AM

Date Purchased Where Purchased Accessories **Original Owner** Y

JERRY S SPORT INC CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/7/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Per Ilion, replace TPA, test at 1/2 normal price

> Repair/Replacement Repair/Replacement Cost Date

10/26/10 Sending ARS.cm 11/8/10 Per Ilion, could not duplicate concern. Check over, clean, replace TPA and test fire at 1/2 normal charges.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner	·	B.TRAVIS
	Exam Date		11/4/2010
	Product Type		RF
	Action Type		Α .
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		20" 243 WIN SS
Barrel	Date Code		KW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4844&Type=Case

11/8/2010

Printl)isplay			
PrintDisplay BARBER	. Kinzer PPS	GAI RE	0009525

DAILDE	K - KIIIZEI PPS GAL KI	L 0003323	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	•
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD M/7 SAFETY
Safety	Function	Select	
	Lift	Select	.012
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	Faise
Feeding Test	16363	False	
Trigger	Condition	Like new; Functioning	
	Pull	Select	5#
	Altered	False	
	Sub-Assembly	Other Remington	



	配© Nov	زَدَ	1	VI	
	NOA	-	5	2010	: -
В	Y:				

emington_®

October 26, 2010

Forest Roberts, Jr 3616 N. Calhoun Hwy Grantsville, WV 26147

Subject: #4844, Model 7

Dear Mr. Roberts,

Per our conversation, enclosed is a prepaid UPS ground shipping label for shipment of the firearm to our factory. Please include a copy of the attached letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Supry".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

S7646920



could not dup heate concern. checkouen, clear, Replace TPA + Test Risce at 1/2 Dormal changes.

Quale

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025 Phone 800-243-9700 • www.remington.com

NOTE: Please complete and print this form, and then include it with your firearm.

	Model Number: MODEL Seven	Serial Number: 57646920				
	Are you the original owner?: YES NO					
	Name: Forest Roberts Tr. Date of Purchase:					
	Address (no PO Boxes): 36/6 North	CALLDUN HWY.				
	city: Grantsuille	State: 1.U. U. Zip: 26147				
	Phone (Daytime): 1-304-354-75/9	Fax:				
		all Address:(if e-mail address is provided, notification of receipt and shipment will be				
E-mail Address: Sent 1						
	GUN WENT OFF WHEN	took OFF SAFTY BS; HON.				
GUN WENT OFF WHEN TOOK OFF SAFTY POSITION. WASN'T OUT OF BOX +911 2009						
	500 characters left					
	Ammunition Information:	and the second second				
	Manufacturer Remington	Type: EXPress B:818				
		100 Gr.				
	The state of the s					
V wan	t a new	Powder Weight:				
trigger &	nstalled	Primer Used:				
Cens Co	Ol me will	Reloader Used:				
Lnie						
July .						
		RARRER - Kinzer DDS GAL RE 00095				



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	10/26/2010 REQUESTED BY:	christy	
QUANTITY:	1 WEIGHT PER PACKAGE		10
LITE YOU OF EAK ONES!			
MEDIA			
COORDINATOR		XXXX	
TO MAIL	I WILL MAIL		
DESCRIPTION:			
Model 7			
S7646920			

LABEL INFORMATION

MAIL LABEL TO:	Forest Roberts, Jr. 3616 N. Calhoun Hwy Grantsville, WV 26147		
RETURN ITÉM TO	: Rem Product Service	·	

PLEASE COMPLETE ALL PARTO OF THIS FORM, AND SEND TO THE MEDIA COORDINATIOR