				Pro	ton Arms Co., In oduct Service	nc.						
				Leg	al Case #:4887							
Case Inform RE# 211200 Customer I	Date 11/2	Opened 22/2010	Date Opene 10/28/20		Date Closed 11/23/2010	Inc	ident D	ate	Pre	Lit I	lit	Obsolete
		¹ First Name	Last Name	Str	·eet	City	State	Zip	Age		Conta	ict
Incident		Bill	Bennett	37230 Fruitl	and Mesa Rd	Crawford	СО	81415	-		70-921 sallv@	1-3971 outdrs.net
Incident Int	formation											
Claims PI			Codes		Rep	air Est.	Med	ical Tr	eatmer	lt i	Medic	al Status
PD S C FSR			Could Not Dupl Fired on Safe Re		l			Unkno	wn			
10/28/10: 0			ated that he had I		÷	•						
Firearm Inf	and an and the second and second a	er hom måsster mense om somsternasse av somsterna	an a sheke ne ya mura mana ma a dawan sa mana a wa sasa									·
Mf Remin	-		Туре CF/BA		Model/ 700/22-250			KU Va		Serial 6713225	Bbl. AV	
Date Pur	chased		Where Purchase Y SPTG GDS DI		Accesso	ries	Origina	i <mark>l Own</mark> e Y	er			
CONCERN	N:FSR,SAI	FETY UPDAT										
Ammunitio	on Informa	tion - None De	fined									
Other Prod	ucts Inform	nation - None I	Defined									
Settlement												
				Remin	igton/700/CF/B/	4						
S	ettlement	R	elease of Claim	s Re	elease Date	Reimbur	semen		Cash lement			Cash Date APV
Per Ilion under	- quote to BLM prog	repair ram										
			pair/Replaceme Cost	nt Repai	r/Replacement Date							
			\$45.23	-	1/29/2010							
		RS, letter, form er BLM progra	-		d not duplicate		-	-			-	

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner]	B.TRAVIS
	Exam Date]	11/23/2010
Examination	Product Type]	RF
	Action Type]	A
	Assigned To]	T.NAGLE
Cause	4038	Could Not Duplicate Concern	POOR MAINTENENCE
	Description]	24" 22-250 REM HB
	Date Code]	AV
	Bore Plugged	False]
Barrel	Bulged	False]
	Fired	False	
	Fired while Obstructed]	
	Muzzle/Crown Condition	Slightly Worn; Functioning]

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4887&Type=Case

11/29/2010

Page 1 of 2

BARBER - Kinzer PPS GAL RE 0009887

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Slightly Worn; Functioning	VERY DIRTY,STICKY
Trianan	Pull	Select	2.5#
Trigger	Altered	Тпие	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4887&Type=Case

- -

11/29/2010

BARBER - Kinzer PPS GAL RE 0009888

frmRepair₩ File Add R		Cl Repairs Estimate Re		dite Repair	Inquiry	Repair Tools			Table Maintenance	System	Location	
		epair Number: F /erify.Repair: NDDRESS INFOR Ci	EOD21120	10.110 Martin	A6713225 M TEM Produc	Iodel 700 Center ed. 03/09/1979 S	m ⁱ Retur	A MARINE AN	ApprovalHold 1172472 AM	2010 6:22:28 eceived from		
			BILL BENNETT				BILL BENNETT 37230 FRUITLAND MESA RD				The second se	
يود		Address 2	ZJUFNUHCA		PO Box:			THUI DAND MES	FO Box			
		Market Color	AWFORD		<u>1997 - 1997 - 1997 - 1</u>		CRAW	FORD	2000 Port 1			
		State C) Zip Code	81415	– Čountry	US Creek	, <u>(</u>	Zip Code: 8141	5 Country US			
		ontact / Condition 1) ate (1)/22/2010 9 11/22/2010 9 11/24/2010 5 11/24/2010 6 11/24/2010 6 11/24/2010 6	Code New Expedite Maint Estimate	49. A. A. A.	Desc1 Repair Ad From: Che	ded ck.ln intenance Jpdate	Desc2	 ☐ Shipping Hai ☐ Inteiface Hai ☐ Estmate Sen ☐ Parts Receiv ☐ Parts Receiv ☐ Parts Receiv ☐ Parts Receiv ☐ Has Been Ap ☐ Has Been Ap ☐ Inteinal Repeir ☐ Exclude TAT 	Appro T11/24/201 Tra- Appro clion cayed Current I proved Transfer	0.6.22.28 AM visbw veFlack ocation LN		
		Repair Sear	ch						Refres	h d	lose	
		•••				and the second secon				in the second		
9(rmRI)#		X			mREL .	DEX)				- increase - day -		
nagletj - ILN	/Prod.c		frmRep	airMain		Meller Carde	NAGLETJ;		Wédnesday, Nov 2	4 2010	8:05 AM	
start 👘		🕏 10 Mi 🔸	😍 frmRep	📬 Part S	e	5 Mic 🗣	a 2 Win +	E Screen	📰 DMS 🛛 😰	АКО-Р.	િકે 🖸 •	и д. 18:26 АМ

,

** <u>*</u> *

	EC	ĮĒ	1	了 2010	Ī
Ш	Nov	2	9	2019	\mathbb{J}
B	Y:				

COPY/ ,010

October 28, 2010

Bill Bennett 37230 Fruitland Mesa Rd Crawford, CO 81415 Ph: 970-921-3971

Ref: #4887, Serial# A6713225

Dear Mr. Bennett,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Mr. Supry will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700 Fax: 336-548-7872

> Could inot Luplicate concern. T.A. dinty + sticky, set sciews altered. Replace TPA, cleAN + TROTFINE under BLP Ron 10 70.00 + ship

Quite

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com



-



	LA NUME IN ATTER ADDING
NOTE: Please complete and print this form, and then inc	A C H G Return for grevious Particle Return for grevious Partic
Model Number: 4071322570	COBDL Serial Number: 176713225
Are you the original owner?: 🗍 YES 🛛 🕅 N	D
Name: Bill Beinett	Date of Purchase: 2 1997
Address (no PO Boxes): 37230 Frail	Tland Mesa Rd.
City: Crau: Ford	State: () Zip: <u>\$/4/5</u>
Phone (Daytime): 970-93/-3971	State: Cip: State: Fax: Image: Cip: State: Intervent State: State:
E-mail Address:(if e-mail address is provided, noti sent)	moeden of receipteric empiricate war be
E-mail Address: i I would like to receive future e-mail updates fro	om Remington.
Please describe your problem and date of occur the rifles set for	rrence: Ireds to be explated
500 characters left Ammunition Information: Press Brisss 4	Car, H380-55gr. Hornady VMX
Manufacturer:	Туре:/
Manufacturer: Other (i.e. bullet weight/type, shat size, powder):	Type:
Manufacturer: Other (i.e. buliet weight/type, shot size, powder): Handload Information:	lype:i
Manufacturer: Other (i.e. bullet weight/type, shat size, powder): Handload Information: Powder Used:	Powder Weight: HC.gt.
Manufacturer: Other (i.e. buliet weight/type, shot size, powder): Handload Information:	Powder Weight: <u>HC.gt.</u>
Manufacturer: Other (i.e. bullet weight/type, shat size, powder): Handload Information: Powder Used: Case/Hull Used: Bullet Type/Shot Size: <u></u>	Powder Weight: <u>HC.gt.</u>
Manufacturer: Other (i.e. bullet weight/type, shat size, powder): Handload Information: Powder Used: Case/Hull Used: Bullet Type/Shot Size: <u></u>	Powder Weight: <u>HC.gt.</u>
Manufacturer: Other (i.e. bullet weight/type, shat size, powder): Handload Information: Powder Used: <i>If 382</i> ² Case/Hull Used: <i>If 382</i> ² Bullet Type/Shot Size: <i>If concert VMX</i> 55 g	Powder Weight: HO.gt
Manufacturer:	Powder Weight: <u>HC.gt.</u> Primer Used: <u>CCT</u> r. Reloader Used: <u>RCBS recKchacker</u> <u>C-RIC</u> per of rounds) <u>20.3C is its</u>
Manufacturer: Other (i.e. bullet weight/type, shat size, powder): Handload Information: Powder Used: $ff 382^{2}$ Case/Hull Used: $ff 382^{2}$ Bullet Type/Shot Size: $ff_{c::nacl_{f}} Vff f 55^{2}$ Firearms Care (Cleaning and Lubrication): Brand of cleaning solution used: $f_{3c} Vff f 55^{2}$ How often do you clean the bore? (Months or Numb- How often do you clean the action? (Months or Numb-	Powder Weight: <u>HC.gt.</u> Primer Used: <u>CCT</u> r, Reloader Used: <u>RCBS</u> r.c.Kchc.K++- <u>CRIC</u> per of rounds) <u>2C.3C.</u> r.c. <u>S.</u> mber of rounds) <u>5C.</u> r.c. <u>S.</u>
Manufacturer: Other (i.e. bullet weight/type, shat size, powder): Handload Information: Powder Used: Case/Hull Used: Case/Hull Used: Bullet Type/Shot Size: Firearms Care (Cleaning and Lubrication): Brand of cleaning solution used: How often do you clean the bore? (Months or Numb	Powder Weight: <u>HC.gt.</u> Primer Used: <u>CCC</u> r. Reloader Used: <u>RCBS</u> r.c.Kehc.K+++ <u>CR/C</u> per of rounds) <u>26.30 r.cls</u> nber of rounds) <u>56 r.cls</u>
Manufacturer: Other (i.e. bullet weight/type, shat size, powder): Handload Information: Powder Used: $\frac{1}{1286^2}$ Case/Hull Used: $\frac{1}{1286^2}$ Bullet Type/Shot Size: $\frac{1}{16666666666666666666666666666666666$	Powder Weight: <u>HC.gt.</u> Primer Used: <u>CCT</u> r. Reloader Used: <u>RCBS recKchacker</u> <u>C-R/C</u> per of rounds) <u>CCSC is its</u> inber of rounds) <u>SC recks</u>

http://www.remington.com/support/repair_services/factory_repair_form.asp

11/24/2009

BARBER - Kinzer PPS GAL RE 0009892

- -

,	a reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?
	is the last time that your firearm was serviced by a Remington authorized n/gunsmith?)
What we	re the services performed?)
Ship you	INSURED firearm by either UPS or Parcel Post to:
A 14	emington Arms Co., Inc. ttn: Arms Service Division 4 Hoefler Avenue on, NY 13357
FIREARM THEM IN	NING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND IUMBER OF YOUR FIREARM.
:: Pack yo ship in a :: Remove :: Provide return a :: Ship yo	the serial number of your firearm before sending it. ur firearm for safety and to prevent further damage in shipping and handling. Preferably, firearm box. (Note: Original boxes may not be returned.) all accessories from your firearm to prevent loss or damage. a return address on both the outside and Inside the box. Shipments without a proper differess will be refused. ur INSURED firearm by either UPS or Parcel Post. Remington is not responsible for or loss during shipment, so you may elect to purchase insurance from your cartier.
Charge re	pairs will be processed using the following guidelines:
	\$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your I number and expiration date with your gun)
You will hi Express, I	airs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping ave 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amou a billed to your credit card. We process checks electronically through Check21.

© 2009 Remingion Arms Company, Inc. All Rights Reserved. Investor Relations | Other Remington Brand Products | Legal Notices | About Us Visit Our Other Websites



http://www.remington.com/support/repair_services/factory_repair_form.asp

11/24/2009

.



www.remington.com

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		10/28/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACK	A 10 lbs
RUEASEICHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref# 4887 Rifle S# A6713225			

LABEL INFORMATION

MAIL LABEL TO: Bill Bennett 37230 Fruitland Mesa Rd Crawford, CO 81415 Ph: 970-921-3971

RETURN ITEM TC Remington Arms Attn: Product Service Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM: AND SEND TO THE MEDIA COORDINATION

ALL CURR USD 1 OF 1 4XX596 SVC GNDCOM OCT 28, 2010 ALL CUR ACT UT 10.0 LBS TRACKINC# 124XX5969065427340 REF 1:BILL BENNETT/CD/DMF REF 2:4887 RIFLE/A6713225 HANDLING CHARGE 6.00 SVC T/P USD STNGLE-PIECE PUB RATE CHROS: COD 0.00 RS 0.50 SD 0.00 DV 0.00 DGD 0.00 00 0.00 SP 0.00 0.00 AH 0.00 TOT PUB CHG 10.59 PR PUB+HANDLING 10.59









