BARBER - Kinzer PPS GAL RE 00100 Arms Co., Inc.

Product Service Legal Case #:5223

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 217149 1/3/2011 11/29/2010 1/6/2011

Customer Information

Contact **Business** First Name Last Name Street City State Zip Type Age Bouchard 75 Cummings Rd Ware 01082 C 413-221-9666 Incident Roger MA

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern

S Fired on bolt closing C

Concern:1008 Fired on Bolt Closing

Unknown

C

11/29/10 Per call from Bouchard, he owns a rifle that was passed down to him from his father who was the original owner. About 10 years ago he took it out and it fired when closed the bolt two times in a row. He took it home to his Dad and he shot it 8 times and it never happened. He put it in the safe after that and has not used it. He now wants to have it checked out so that his daughter can use it.cm

Firearm Information

DOM Model/Ga. SKU Serial Bbl. Mfg. Type CF/BA 700/270 WIN 25791 B6827800 RC 11/24/1986 Remington **Date Purchased** Where Purchased Accessories **Original Owner MATHEWS & BOUCHER** SCOPE BASE N

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Settlement Date APV Date APV

Per Ilion, replace TPA, clean, test fire at 1/2 normal cost

Repair/Replacement Cost Repair/Replacement Date

11/29/10 Mailing ARS.cm 1/14/11 Per Ilion, could not duplicate concern. Trigger assm set screws altered, trigger has min. return. Replace TPA, clean and test fire at 1/2 normal cost. I called Bouchard and he says they have not altered. He wants it returned unrepaired and he will have a local gunsmith check it. I told him to sign the quote and notate that he did not want it repaired and then I will ship it back to him.cm 1/24/11 Bouchard called and wants us to repair it. He's changed his mind.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date		1/6/2011	
Examination	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4038	Could Not Duplicate Concern		
	Description		22" 270 WIN	
Barrel	Date Code		RC	
	Bore Plugged	False		
	Bulged	False		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5223&Type=Case

1/24/2011

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overali	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	MIN TRIG RETURN
Tui a san	Pull	Select	3#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

22 pc 1/86

5223

November 29, 2010

Roger Bouchard 75 Cummings Rd Ware, MA 01082

Subject: #5223, Model 700

Dear Mr. Bouchard,

Enclosed is the prepaid UPS ground shipping label. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service". Apply the label to your box and take it to a UPS terminal or driver for shipping.

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com 10 JAN 1 2 2011

BY:____

B6827800 Model: 700 RE00217149 could not duplicate between T.A. set Schus altered,
TRIQ HAS MIN HETURN.
Replace TPA, CLANT TEST RIPE
AT 1/2 Nonmal LOST.

Q note

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

2) O

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700 270W.F	Serial Number: B6827800				
Are you the original owner?: YES X NO	my father was				
Name: Roger Bouchard 0	Date of Purchase:				
Address (no PO Boxes): 75 Cummings	Rd.				
City: Ware	State: MA. Zip: 01082				
Phone (Daytime): 1-4/3-221-9666	Fax: 1-4/3-967-6786				
E-mail Address:(if e-mail address is provided, notification	n of receipt and shipment will be				
sent)					
E-mail Address:					
I would like to receive future e-mail updates from Re	emington.				
Please describe your problem and date of occurrence	e:				
of closed the Bolt gun fired					
and time closed the foit god fire	d.				
200 Time closed the 1001					
put our in safe until M	<i>•</i>				
when it did it it was	Real coid				
500 characters left					
Ammunition Information:					
Manufacturer:	Type: I				
Other (i.e. bullet weight/type, shot size, powder):					
Handload Information:					
Powder Used: I	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				

BARBER - Kinzer PPS GAL RE 0010060

	Case#	5221	Date of Call	11/29/16			PreLit Lit	Obs	
	Reporter name address contact #'s			·	Incident Name/Age address contact #'s	Rog 75 Wa	er Bouch Cumpin re, MA 413-22	lard s Rd 01082	
	email				email	Cell	413-28	4-7666	
	Injury Medical Treatment								
	Alleged cause				Orig				
	Firearm 760	Ser# B6827800	Cal	DOM -87	owner?	When/W	here purchased	father orig	· confer
<u>)</u>)	Ammunition	Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot#	Additional info		
ļ	Other Product								
Fired on bolt closing, couple times. His daughter wants to shoot, wants it checked Satisfic safe for 10 yrs after that happened									
	Notes: Customer's								
	Request My actions/ offers								



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	11/29/20	010 REQUESTED BY:	christy
QUANTITY:		1 WEIGHT PER PACKAGE:	10
PLEASE CHÉCKONE : MEDIA COORDINATOR			
TO MAIL		1 WILL MAIL	xxxxx
DESCRIPTION:	7	700	
	B6827800		

LABEL INFORMATION

MAIL LABEL TO:	Roger Bouchard	- · · · · · · · · · · · · · · · · · · ·	
	75 Cummings Rd		
	Ware, MA 01082		
			•
RETURN ITEM TO	: Rem Prod Service		

PREASE COMPLEME ALL PARTISTOF THIS FORM: AND SEND TO THE MEDIA COORDINATION

4XX596 NOV 30, 2010 ALL CURR USD 1 OF 1
SVC GNDCOM ACT UT 10.0 LBS
TRACKING# 1Z4XX5969067460256
REF 1:ROGER BOUCHARD/CD/CM
REF 2:700/B6827800

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 7.24 PUB+HANDLING 7.24





