Remington Arms Co., Inc. Product Service Legal Case #:5500

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 218315
 1/10/2011
 12/28/2010
 1/11/2011

**Customer Information** 

Last Name Street City Type **Business** First Name State Zip Age Contact H 828-633-2171 8 Oak Terr. Dr. Incident Tony DeBruhl Asheville NC 28806 C 828-674-9064 E tddebruhl@yahoo.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4015 Improper Maintenance S Concern:1020 Fired on Bolt Opening

Concern:1020 Fired on Bolt Opening

Unknown

C FBC

12/28/10: Customer called in. He stated that he had a FBC last year. No damage, No injury. He saw the tv show. df

Firearm Information

Model/Ga. SKU DOM Type Serial Mfg. Rhl. CF/BA 700/25-06 REM n/a 6324078 3/1/1970 Remington ΑT **Date Purchased** Where Purchased Accessories Original Owner N

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Settlement Date APV

Per Ilion - Quote to repair under BLM program

Repair/Replacement Cost Date
\$77.90 1/20/2011

12/28/10: Sending ARS, ltr, form. df 1/20/11: Per Ilion - Will follow down. TA very dirty & sticky causing parts to work sluggish. Replace TA, clean & test fire under BLM program - quote. I left a message for cust. to call me. df 1/21/11: Customer called. He approved quote to repair. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date	]	1/11/2011	
Examination	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4015	Improper Maintenance		
	Description		24" 2506 REM	
	Date Code	]	AT	
	Bore Plugged	False		
	Bulged	False		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5500&Type=Case

2/2/2011

1	Fired	False	1
Barrel	Fired while	l raise	1
	Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Worn; Functioning	CRACKED, APPEARS FROM NOT HAVING MAG BOX IN PLACE DURING ASSM SCREW THAT HOLDS MAG BOX IS BROKEN
L	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new: Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.007
	Notch	Slightly Worn; Functioning	BINDS TO SIDEPLATES
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY.SEAR BINDS TO SIDEPLATES
	Pull	Select	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

COPY

24" 1/3/70 3.5" 100'7

5500

December 28, 2010

Tony DeBruhl 8 Oak Terrace Dr. Asheville, NC 28806 Ph: 828-633-2171

Ref: #5500

Dear Mr. DeBruhl,


Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872



6324078 Model: 700 RE00218315 WIll follow down BY:

T.A. VERY dirty sticky chusing
PARTS to work sluggish.

Replace TPA, clean + Test fire
UNDER BLP for \$ 20,00 + Ship

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Reset

Print

Model Number: 700	Serial Number: 6324078					
Are you the original owner?:   YES  NO						
Name: TONY DEBRUAL	Date of Purchase:					
Address (no PO Boxes):						
City: Asheville	State: NC Zip: 28806					
Phone (Daytime): \$28 633 2/7/	Fax: 1//A					
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent) TD De BRUHL A) YAhoo, COM						
E-mail A	ddress:					
Please describe your proble	m and date of occurrence:					
When Ever you Bolt The gun It FIRES						
:500 cha	racters left					
Ammunition Information:						
Manufacturer: Hornaday	Type: 25.06					
Other (i.e. bullet weight/type, shot size, powder):						
Handload Information:						
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size:	Reloader Used:					
Firearms Care (Cleaning and Lubrication):						

http://www.remington.com/asp/factory\_repair\_form.asp

12/13/2010

Brand of cleaning solution used: Remington Gun Oil (SPRAY)  How often do you clean the bore? (Months or Number of					
How often do you clean the bore? (Months or Number of rounds) 6 months - 2 Time A VEAR					
How often do you clean the action? (Months or Number of rounds)					
How often do you clean the trigger assembly? (Months or Number of					
rounds) <u>5 A M e</u> Brand of lubricant used: <u>5 A M e</u>					
How often do you lubricate the bore? (Months or Number of rounds)					
How often do you lubricate the action? (Months or Number of rounds)					
How often do you lubricate the trigger assembly? (Months or Number of rounds)					
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES YES NO					
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) 2 Yeans Ago					
What were the services performed?) General Gleaning					
Ship your INSURED firearm by either UPS or Parcel Post to:					
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357					
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.					
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling.  Preferably,  ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper					

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:		12/28/2010	REQUESTED BY:	Dell
QUANTITY:	1		WEIGHT PER PKG:	10 lbs
PLEASEIGHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref # 5500 rifle			

## LABEL INFORMATION

MAIL LABEL TO: Tony DeBruhl
8 Oak Terrace Dr.
Asheville, NC 28806
Ph: 828-633-2171

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

## REPASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

```
DEC 28, 2010 ALL CURR USD
ACT UT 10.0 LBS
                                                                  1 OF 1
4XX596
SVC GNDCOM
SVC GNDCOM RC1 M1
TRACKING# 1Z4XX5969066694550
REF 1:TONY DEBRUHL/CD/DMF
REF 2:5500/RIFLE
HANDLING CHARGE 0.00
                                                     SVC T/P USD
SINGLE-PIECE PUB RATE CHRGS:
                  COD 0.00
                                                       RS 0.50
SD 0.00
DV 0.00
DC 0.00
                             DGD
                                     0.00
                                                       SP 0.00
                                      0.00
                             PR
AH 0.00
TOT PUB CHG 8.78
                                     PUB+HANDLING
```

