Remington Arms Co., Inc. **Product Service** Legal Case #:5079

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

11/12/2010

Customer Information

Type Business First Name Last Name Street City State Zip Contact Age

Incident

1805 Virginia Place Joseph Doty

76033 Cleburne ΤX

H 817-517-9688

Incident Information

Codes Claims

Repair Est. Medical Treatment Medical Status

PI

PD Shot hole in deer

stand

Cause:4079 Other - Unexamined Concern: 1007 Fired on Safe Release

Unknown

S C FSR

11/12/10: Cusotmer called in. He stated he had a FSR & shot a hole in his deer stand this year. He has been talking to his friends & has been on the internet. He feels that we have a problem & we need to take care of it before someone else gets killed, df

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CF/BA

700/308 WIN

85469 S6694263 4/23/2009 9:23:22 AM

Date Purchased

Where Purchased

Accessories Original Owner

CABELA S INC/WAREHOUSE /

Y

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date

APV APV

Repair/Replacement Cost

Repair/Replacement

Date

11/12/10: Sending ARS, ltr, form. df

Examination[Remington/CF/BA]

Sub-Part Code Comment **Part**



4

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/16/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACKA(10 lbs	
PLEASE CHECKON MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref# 5079 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Joseph Doty
1805 Virginia Pl.
Cleburne, TX 76033
Ph: 817-517-9688

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PLEASE COMPLETE ALL PARTISION THIS FORM; AND SEND TO THE MEDIA COORDINATION

4XX596 NOV 17, 2010 ALL CURR USD 1 OF SVC GNDCOM ACT WT 10.0 LBS
TRACKINGH 1Z4XX5969066357594
REF 1:JOSEPH DOTY/CD/DMF
REF 2:5079/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DC 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 9.45 PUB+HANDLING 9.45