

GUN # - XC 1057
DATE - 5-20-99
SHOOTER - JH

M/710 EET SAMPLE RIFLES
100 ROUND PROOF TEST

TRACKING # TLW 9142G
PROJECT # 241095

AMMO		REM	PRF 30-06	LOT #		D 17C A0726
		MALFUNCTIONS		INS.		MALFUNCTIONS
1	1	HEADSPACE	MIN + .002	✓	51	1
2	2	HEADSPACE	.002	✓	52	2
3	3	HEADSPACE	.002	✓	53	3
4	4	HEADSPACE	.002	✓	54	4
5	5	HEADSPACE	.002	✓	55	5
6	6	HEADSPACE	.002	✓	56	6
7	7	HEADSPACE	.002	✓	57	7
8	8	HEADSPACE	.003	✓	58	8
9	9	HEADSPACE	.003	✓	59	9
10	10	HEADSPACE ✓	.003	✓	60	10 ✓
11	1				61	1
12	2				62	2
13	3				63	3
14	4				64	4
15	5				65	5
16	6				66	6
17	7				67	7
18	8				68	8
19	9				69	9
20	10	HEADSPACE ✓	.003	✓	70	10 ✓
21	1				71	1
22	2				72	2
23	3				73	3
24	4				74	4
25	5				75	5
26	6				76	6
27	7				77	7
28	8				78	8
29	9				79	9
30	10	HEADSPACE ✓	.003	✓	80	10 ✓
31	1	Sear pin fell out of fire control - nut came loose on screw - trigger pin loose - trigger fell out			81	1
32	2				82	2
33	3				83	3
34	4				84	4
35	5				85	5
36	6				86	6
37	7				87	7
38	8				88	8
39	9				89	9
40	10	HEADSPACE ✓	.003	✓	90	10 ✓
41	1				91	1
42	2				92	2
43	3				93	3
44	4				94	4
45	5				95	5
46	6				96	6
47	7				97	7
48	8				98	8
49	9				99	9
50	10	HEADSPACE	.004	✓	100	10 HEADSPACE ✓ .004

Ins. = Inspected w/ bore scope chamber, lugs

Look at firing pin, extractor belt lugs