Page 1 of 2 **PrintDisplay** 

### BARBER - Kinzer PPS GAL RE 0012380

Remington Arms Co., Inc. **Product Service** Legal Case #:5369

Case Information

Date Opened(PS) **Date Closed** Incident Date Obsolete RE# **Date Opened** Lit Pre Lit

12/9/2010 1/6/2011 217093 1/3/2011

Customer Information

First Name Last Name Street City State Zip Contact Business Age H 405-372-5276 811 E. Tower Park Dr. Incident Ralph Sprangers Stillwater OK 74075

E jrsprang71@brightok.net

Incident Information

Repair Est. Claims Codes Medical Treatment **Medical Status** 

ΡI

PD Cause: 4006 Altered Adjustments or Components Concern: 1007 Fired on Safe Release

Unknown

**Original Owner** 

S C FSR

Customer sent in an email. He stated he was sighting gun in sometime in November and he had a FSR. No damage, No injury. df

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type 700/3006 SPRG CF/BA n/a 6811129 CZ 4/1/1975 Remington

**Date Purchased** Where Purchased Accessories

POINT SPT GDS STEVENS PT WIS Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Cash Reim. Settlement Release of Claims Release Date Reimbursement Date Settlement Date APV APV

Per Ilion - Quote to repair under BLM program

Repair/Replacement Repair/Replacement Cost Date

1/19/2011 \$75.16

12/9/10: I will email ltr & form. I will ask media coord. to email ARS. df 1/19/11: Per Ilion - Will follow down. Sear engagement screw altered. TA dirty. Replace TA, clean & test fire under BLM program - quote. I called customer. Wife said she mailed payment on 1/18/11. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/6/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
ВагтеІ	Description		22" 3006 SPR LH
	Date Code		CZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5369&Type=Case

1/19/2011

	Muzzle/Crown Condition	Slightly Worn, Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trianna	Condition	Slightly Worn; Not Functioning	DIRTY
	Pull	Select	1.2#
Trigger	Altered	True	SEAR ENGAGEMENT ALTERED
	Sub-Assembly	M/700 Bolt Lock	

# Remington.

22" (24/7)

5369

December 9, 2010

Ralph Sprangers 811 E. Tower Park Dr. Stillwater, OK 74075 Ph: 405-372-5276 Email: jrsprang71@brightok.net

Ref: #5369


Dear Mr. Sprangers,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872



BY:

enclosure

題6811129 Model: 700

RF00217093

Will follow down.
SEAR ENGAGEMENT SCIEW Altered.
T.A. DIRTY. Replace TPA clean
+ Test Rize under 3LP for
\$ 20.00+ 5hip
Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

35 1

<u>Print</u>	_Reset_]	
Model	Serial	
Number: 700 L H	Number: 6811129	
Are you the original own	ner?: 🗹 YES 🖾 NO	
Name: RALPHSprangers	Date of Purchase:	
Address (no 811 E. Tower Park	PO Boxes): DR.	
City: ST: 1/44aTer	State: OKIA, Zip: 74075	
Phone (Daytime): 405-372-5076	Fax:	
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)irsprana71@brightok.net		
E-mail A	e-mail updates from Remington.	
Please describe your problem and date of occurrence:  Put one rannow thought to chambed it is chambe		
Ammunition Information:		
Manufacturer: BEming TON Type: CorE-LoKT		
Other (i.e. bullet weight/type, shot size, powder): ノル ケーノ8の g い		
Handload Information:		
Powder Used: —	Powder Weight:	
Case/Hull Used:	Primer Used:	
Bullet Type/Shot Size:	Reloader Used:	
Firearms Care (Cleanir	ng and Lubrication):	

http://www.remington.com/asp/factory\_repair\_form.asp

12/6/2010

Brand of cleaning solution used: Hopes
How often do you clean the bore? (Months or Number of rounds) 3To 4 Timesa Year
How often do you clean the action? (Months or Number of rounds) 3704 Trmes YR
How often do you clean the trigger assembly? (Months or Number of rounds) ノミルとトソコ YRS
Brand of lubricant used: Hoppes Gun oil
How often do you lubricate the bore? (Months or Number of rounds) 3 - 4/ YR
How often do you lubricate the action? (Months or Number of rounds) 3 - ム スター
How often do you lubricate the trigger assembly? (Months or Number of rounds) レビュンスパリ
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES INO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a

12/09/2010 10:07 AM

11/29/2010 10:26 PM

#### BARBER - Kinzer PPS GAL RE 0012385

Reference # 101129-000196

**Status** Waiting

**Assigned To** Administrators

Dell -**Product** 

Firearms SLA

Not specified

Queue **CSR** 

**Date Created** 11/29/2010 10:26 PM

Initial Response 12/09/2010 10:07 AM

Last Updated 12/09/2010 10:07 AM

**Customer SmartSense** +1 (on -3 to +3 scale)

Staff SmartSense +1 (on -3 to +3 scale)

## Remington 700

### **Discussion Thread**

Response (Dell -)

Dear Mr. Sprangers,

We would like to have the firearm come into our Product Services Department at our factory for examination. We will send you a pre-paid shipping label for UPS to have the firearm come in. I will also include a form that you can fill out to let the examiner know exactly what happened, when this occurred, and what you are expecting.

Sincerely, Dell

## Customer (1 jrsprang71@brightok.net)

To Whom It Concerns,

Sirs, about 2 weeks ago as I was going to site in my Remington 700. I pushed the safety from on position to fire position and the gun fired without pulling the trigger. Then I did the same procedure two more times and it did the same thing. The next four rounds when I chambered the round the gun fired without pulling the trigger or moving the safety. Then I came home and just cocked the empty gun and pushed the bolt down and it fired. Then I did two more times and it did the same thing.

I'm 63 years old, I've been trained in the United States Army, I've hunted since I was 8 years old so I don't want any garbage about not being experienced on handling guns. I also helped train students for hunter safety courses.

This is my 30-06, will my 300 Mag. do the same thing? They are both 700s. I now refuse to use the 30-06 in the shape it is in and refuse to take it hunting. I expect a reply from you on how you are going to repair this gun for me. Will be waiting to hear from you.

Ralph Sprangers 811 E Tower Park DR Stillwater, OK 74075 405-372-5276

## **Primary Contact**

First Name: 1

Last Name: jrsprang71@brightok.net

Organization:

Login: jrsprang71@brightok.net

Title: Contact Type:

Email: jrsprang71@brightok.net

Email - Alternate #1: Email - Alternate #2: Office Phone:

Mobile Phone: Fax: **Assistant Phone:** Home Phone:

> Street City State/Province **Postal Code** Country

Additional Information

December 9, 2010

Ralph Sprangers 811 E. Tower Park Dr. Stillwater, OK 74075 Ph: 405-372-5276

Email: jrsprang71@brightok.net

Ref: # 5369

Dear Mr. Sprangers,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure



December 9, 2010

Ralph Sprangers 811 E. Tower Park Dr. Stillwater, OK 74075 Ph: 405-372-5276 Email: jrsprang71@brightok.net

Ref: #5369

Dear Mr. Sprangers,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

Fax: 336-548-7872

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

enclosure

Reset

## BARBER - Kinzer PPS GAL RE 0012388

Print

Model	Carlo			
Number:	Seria Number:	:		
Are you the original owner?: 🖺 YES 🖺 NO				
Name:	Date of Pur	rchase:		
Address (no	PO Boxes):			
City:	State:	Zip:		
Phone (Daytime):	Fax:			
E-mail Address:(if e-mail address is provided be sent)	led, notification of receipt	and shipment will		
E-mail A				
I would like to receive future				
Please describe your problem and date of occurrence:  500 characters left				
Ammunition Information:  Manufacturer: Type:				
Other (i.e. bullet weight/type, shot size, powder):				
Handload Information:				
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			
Firearms Care (Clean	ng and Lubrication):			

## BARBER - Kinzer PPS GAL RE 0012389

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
□ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

### **BARBER - Kinzer PPS GAL RE 0012390**

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express. Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

## BARBER - Kinzer PPS GAL RE 0012391 Fulcher, Dell Marie

From:

postmaster@remington.com

To:

jrsprang71@brightok.net

Sent: Subject: Thursday, December 09, 2010 12:17 PM Relayed: Ralph Sprangers - Ref# 5369

Delivery to these recipients or distribution lists is complete, but delivery notification was not sent by the destination:

jrsprang71@brightok.net

Subject: Ralph Sprangers - Ref# 5369





Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:	12/9/2010	REQUESTED BY:	Dell
QUANTITY:	1	WEIGHT PER PKG:	10 lbs
REASEICHECKIONE MEDIA COORDINATOR TO MAIL	·		
DESCRIPTION:	Ref # 5369 rifle		
· .	LABEL I	jrsprang71@brig	ghtok.net
MAIL LABEL TO:	Ralph Sprangers 811 E. Tower Park Dr. Stillwater, OK 74075 Ph: 405-372-5276 Email: jrsprang71@brightok.		Email ARS to customer
RETURN ITEM TO	CRemington Arms Attn: Product Service Ilion, NY	4XX596 DEC SVC GNDCOM TRACKING# 1Z4XX59 REF 1:RALPH SPRAI REF 2:5369/RIFLE	969067636898 NGERS/CD/DMF
WRUEASE COMP	ueijealuparisoetihiseor	HANDLING CHARGE	0.00 SVC T/P USD  RATE CHRGS: RS 1.00  COD 0.00 SD 0.00  DGD 0.00 SP 0.00  PR 0.00 ING 9.95

## BARBER - Kinzer PPS GAL RE 0012393

## Fulcher, Dell Marie

From:

jrsprang71@brightok.net

To:

Fulcher, Dell Marie

Sent: Subject: Thursday, December 09, 2010 2:25 PM Read: Ralph Sprangers - Ref# 5369

Your message was read on Thursday, December 09, 2010 2:24:40 PM (GMT-05:00) Eastern Time (US & Canada).

