

Remington Arms Co., Inc.
Product Service
Legal Case #:5335

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
217642	1/6/2011	12/8/2010	1/7/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Robert	Street	9141 Walworth Rd.	Bancroft	MI	48414		H 989-634-5596 C 989-860-1838

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4054 As received Follows Down		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

12/7/10: Customer called in. He stated he had a FSR earlier this year. No date given. No damage, No injury. He saw the tv show & is concerned now. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	n/a	168634	LN	2/1/1966
Date Purchased	Where Purchased	Accessories	Original Owner			
			Y			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM program						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$45.40	1/21/2011				

12/8/10: Sending ARS, ltr, form, box. Box order# 1166466. df 1/21/11: Per Ilion - Will follow down. TA set screws altered. Replace TA, clean & test fire under BLM program - quote. I spoke to customer & he will mail payment w/quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/7/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4054	As received Follows Down	
Barrel	Description		24" 22-250 REM
	Date Code		LN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	---Select---	O/S DOUBLE SLUGGISH
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	1#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

COPY

24"
LN2/66
i#

5335

December 8, 2010

Robert Street
9141 Walworth Rd.
Bancroft, MI 48414
Ph: 989-860-1838

Ref: # 5335

Dear Mr. Street,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700
Fax: 336-548-7872

RECEIVED
JAN 10 2011

BY:

enclosure

will follow down.

*T.A. set screws altered.
replace TPA, clean + test fire
under BCP for \$ 20.00 + ship*

Quote

Serial Number

168634

Model: 700



RE00217642

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

BARBER - Kinzer PPS GAL RE 0012465

Print

Reset

Model Number: <u>REM 700 22-250</u>		Serial Number: <u>168634</u>	
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: <u>ROBERT STREET</u>		Date of Purchase: <u>APR 1967</u>	
Address (no PO Boxes): <u>9141 WALWORTH RD</u>			
City: <u>BANCROFT</u>		State: <u>MI</u>	Zip: <u>48414</u>
Phone (Daytime): <u>989 634 5596</u>		Fax: <input type="text"/>	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) <input type="text"/>			
E-mail Address: <input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: <u>WHEN YOU CLOSE THE BOLT AND</u> <u>TAKE THE SAFETY OFF, THE GUN</u> <u>FIRES.</u> <u>THE FIRST WEEK OF NOV. 2010</u>			
500 characters left			
Ammunition Information:			
Manufacturer: <input type="text"/>		Type: <input type="text"/>	
Other (i.e. bullet weight/type, shot size, powder): <input type="text"/>			
Handload Information:			
Powder Used: <input type="text"/>		Powder Weight: <input type="text"/>	
Case/Hull Used: <input type="text"/>		Primer Used: <input type="text"/>	
Bullet Type/Shot Size: <input type="text"/>		Reloader Used: <input type="text"/>	
Firearms Care (Cleaning and Lubrication): <input type="text"/>			

BARBER - Kinzer PPS GAL RE 0012466

Brand of cleaning solution used:	
How often do you clean the bore? (Months or Number of rounds)	AFTER I SHOOT IT
How often do you clean the action? (Months or Number of rounds)	AFTER I SHOOT IT
How often do you clean the trigger assembly? (Months or Number of rounds)	AFTER I SHOOT IT
Brand of lubricant used:	HOPPE'S
How often do you lubricate the bore? (Months or Number of rounds)	AFTER I SHOOT IT
How often do you lubricate the action? (Months or Number of rounds)	AFTER I SHOOT IT
How often do you lubricate the trigger assembly? (Months or Number of rounds)	AFTER I SHOOT IT
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)	NEVER
What were the services performed?)	
Ship your INSURED firearm by either UPS or Parcel Post to:	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357	
<input type="checkbox"/> WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.	
:: Record the serial number of your firearm before sending it.	
:: Pack your firearm for safety and to prevent further damage in shipping and handling.	
Preferably,	
ship in a firearm box. (Note: Original boxes may not be returned.)	
:: Remove all accessories from your firearm to prevent loss or damage.	
:: Provide a return address on both the outside and inside the box. Shipments without a proper	

Remington.

www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	12/8/2010	REQUESTED BY:	Dell
QUANTITY:	1	WEIGHT PER PKG:	10 lbs
PLEASE CHECK ONE			
MEDIA COORDINATOR TO MAIL		I WILL MAIL	XXXXXX
DESCRIPTION: Ref # 5335 rifle			

LABEL INFORMATION

MAIL LABEL TO: Robert Street 9141 Walworth Rd. Bancroft, MI 48414 Ph: 989-860-1838
RETURN ITEM TO Remington Arms Attn: Product Service Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 DEC 8, 2010 ALL CURR USD 1 OF 1
SVC GND COM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969065955145
REF 1: ROBERT STREET/CD/DMF
REF 2: 5335/RIFLE

HANDLING CHARGE 0.00		SVC T/P USD	
SINGLE-PIECE PUB RATE CHRG:		RS	0.50
DV 0.00	COD 0.00	SD	0.00
DC 0.00	DGD 0.00	SP	0.00
AH 0.00	PR 0.00	PUB+HANDLING 8.20	
TOT PUB CHG 8.20			







