Remington Arms Co., Inc. Product Service

Legal Case #:5193

Case Information

RE# Date Opened 214386

Date Opened(PS) 11/24/2010 12/13/2010

Date Closed 12/15/2010

Incident Date 11/16/2010

Obsolete Pre Lit Lit

Customer Information

Type Business First Name Last Name

Street

City

State Zip Age

Contact

Incident

Donald

118 Radar Rd. Daugherty

Mount Pleasant PA 15666 C 724-972-5838 F 724-628-6321

E donald.e.daugherty@us.army.mil

Incident Information

Claims

Codes

Repair Est.

Medical Treatment

Medical Status

. 450 . 01 -

ΡI

S

PD

Cause: 4038 Could Not Duplicate Concern

Unknown

C FSR

11/23/10: Customer called in. He stated he had a FSR on 11/17/10. No damage - No injury. df

Firearm Information

Mfg.

Type CF/BA

Concern:1007 Fired on Safe Release

Model/Ga.

SKU

Reimbursement

Serial Bbl. DOM

Remington

Where Purchased

700/308 WIN 27359 Accessories **Original Owner** G6938112 LE 2/11/2010 11:50:51 AM

Date Purchased 10/1/2010

ACUSPORT (OH) CORPORATION

Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Release of Claims

Release Date

Cash

Settlement

Reim. Date Cash Date APV APV

Settlement Per Ilion - Repair under warranty

Repair/Replacement Cost

Repair/Replacement

Date

\$52.52

12/29/2010

11/24/10: Sending ARS, ltr, form. df 12/29/10: Per Ilion - Could not duplicate concern. TA is functioning as designed. To restore confidence in rifle - replace TA, clean, & test fire @ n/c - warranty. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/15/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 308 WIN
	Date Code		LE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		-
			 7

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5193&Type=Case

12/29/2010

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning	
L	Fore End Condition	Select	
Desertions	Condition	Like new; Functioning	
Receiver	Bulged	False	
	Description		STANDARD XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.011
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

5193 4 5193

November 24, 2010

Donald Daugherty 118 Radar Rd. Mount Pleasant, PA 15666 Ph: 724-972-5838

Ref: #5193

Dear Mr. Daugherty,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure

G6938112 Model: 700 RE00214386 Trig Assm 1s formetioning AS

Resigned check own cont

TIST fine. At N/c

MATTERIAL DEC 2 2 2010

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

		_
Print	Rese	t

Model	Seri	ial		
Number: 700 SPS	Number: 66938/12			
Are you the original owner?: 🏿 YES 🖺 NO				
Name: Dandada Id	Date of Purchase:			
Name: Daugherty Donald	OCT 2	20/0		
Address (no	PO Boxes):	Tribution to the state of the s		
118 Radar Rd		po man months to a tank to a tank the same of		
City: MT Pleasant	State: PA	Zip: 15666		
Phone (Postimo): 37 070	Fax: 724-628	-6321		
(Daytime): 724 972 5838		<u> </u>		
E-mail Address:(if e-mail address is provid		ot and shipment will		
be sent) donald.e.daugherty@	,			
E-mail A I would like to receive future e		mington.		
Please describe your proble	em and date of occurre	ence:		
	when taken off of safety the gun is discharging on it's own NOV 16 2010 four times			
discharging on it's oc	۸ر			
NOV 16 2010 from 1.		a		
	res.			
500 cha	racters left			
Ammunition I	nformation:			
Manufacturer: Reminston	Type: Core lok			
Other (i.e. bullet weight/type, shot size,				
powder): 150 gs fsf				
Handload Information:				
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			
Firearms Care (Cleaning and Lubrication):				

Brand of cleaning solution used: Rem 0./
How often do you clean the bore? (Months or Number of rounds) Clean before fixing and after 2 misfire
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Rem 0,1
How often do you lubricate the bore? (Months or Number of rounds) აგ განისი
How often do you lubricate the action? (Months or Number of rounds) Same us ക്രാല
How often do you lubricate the trigger assembly? (Months or Number of rounds) Same As Above
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > X YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) Never Brad wew
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/24/2010	REQUESTED BY:	Dell
QUANTITY:	1		WEIGHT PER PKG:	10 lbs
RLEASEICHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref # 5193 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Donald Daugherty
118 Radar Rd.
Mount Pleasant, PA 15666
Ph: 724-972-5838

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PREASE COMPREHENCEPARTS OF THIS FORM, AND SEND TO THE MEDIA COORDINATOR

NOV 24, 2010 ALL CURR USD ACT WT 10.0 LBS 1 OF 1 4XX596 SVC GNDCOM TRACKING# 1Z4XX5969065546604 REF 1: DONALD DAUGHERTY/CD/DMF REF 2:5193/RIFLE HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 COD 0.00 DV 0.00 DC 0.00 0.00 SD 0.00 DGD SP 0.00 0.00 PR AH 0.00 PUB+HANDLING TOT PUB CHG 7.42





