

BARBER - Kinzer PPS GAL RE 0013446 Remington Arms Co., Inc.
Product Service
Legal Case #:5146

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
210778	11/18/2010	11/19/2010	11/19/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City State	Zip	Age	Contact
Reporter	Denny's Guns and Maps		Denny's Guns an	1328 Beck Ave	Cody WY	82414		
Incident		Bill	Mosasky	1326 Rd Butte Ave	Cody WY	82414		H 307-587-9068

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	Fires on bolt closing Concern:1008 Fired on Bolt Closing		Unknown	
C				

12/2/10 per note with rifle, trigger will go off on occasion when bolt is dropped. Please replace trigger with new XMark Pro per customer's request.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	85953	7833281	XB	12/21/2007 10:04:41 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT (OH) CORPORATION		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, check over, clean, test fire no charge as goodwill						
	Repair/Replacement Cost	Repair/Replacement Date				
	27.00	12/2/2010				

12/2/10 Per Ilion, could not duplicate concern. Trigger assm is functioning as designed. Check over, clen and test fire. Rifle shipped back out on 11/23.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS

BARBER - Kinzer PPS GAL RE 0013447

Examination	Exam Date	11/19/2010	
	Product Type	RF	
	Action Type	A	
	Assigned To	T.NAGLE	
Cause	4038	Could Not Duplicate Concern	FUNCTIONING AS DESIGNED
Barrel	Description	22" 22-250 REM CAMO	
	Date Code	XB	
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description	STANDARD XMP SAFETY	
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Location

frmREInquiry - Repair Inquiry

Repair Number: **RE00210778** Serial: 7833281 Model 7, Center Fire Caliber: 22
250REM Produced: 12/21/2007 SKU: 85953 Repairman: _____
Verify Repair Status: **Repairing 11/19/2010 3:09:11 PM**

ADDRESS INFORMATION

Customer: ☐ Received from Return To ☐ Received from

Name: **DENNY'S GUNS AND MAPS** **DENNY'S GUNS AND MAPS**

Address 1: **1328 BECK AVE** **1328 BECK AVE**

Address 2: _____ PO Box: _____ PO Box: _____

City: **CODY** **CODY**

State: **WY** Zip Code: **82414** Country: **US** **WY** Zip Code: **82414** Country: **US**

FFL: _____

Contact / Condition Problems Estimate History / Status Shipping / Billing

Date	Code	UserID	Desc1	Desc2
11/18/2010 7:...	New	lopatali	Repair Added	
11/18/2010 7:...	Update	lopatali	Repair information change	
11/19/2010 3:...	Maint	Travisbw	Repair Maintenance	Status: Repa

Shipping Hold ☐ Interface Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return as Received ☐ Has Been Approved ☐ Internal Repair ☐ Exclude TATC ☐

Current Status

Repairing **11/19/2010 3:09:11 PM**

lopatali

Repair Bench

Repair Location

ILN

Current Location

ILN

Transfer Number

Repair Search Refresh Close

supryfl - ILN/Prod frmRepairMain D1102R7XPIL Thursday, Nov 18 2010 8:43 AM

start DMS - Desktop frmRepairMain - FGI Inquiry - Microsoft

RECEIVED

NOV 23 2010

BY:

22"
XB 12/07
JH
10/12

Warranty Repair Form

Name BILL MOSASKY 5146
 Address 1326 Rd Butte Ave,
Cady, NY, 82414

Phone (307) 587-9068

Item Remington Model 7
SN# 7833281

Problem

Trigger will go off on occasion
 when bolt is dropped.
 Please replace trigger with new
 X Mark Pro. trigger with customers
 request.

Ship

To: DE REMINGTON ARMS
14 HUEFLER AVE.
ILION, NY, 133571816

Return

To: DENNYS GUNS + MAPS
1328 BECK AVE.
CADY, NY, 82414
307-587-3677
Call with questions

Postage

Handling

could not duplicate concern.
 Trig. assm. is functioning as
 designed. checked over, clean
 & test fine.



Model: 7

 Serial Number:
 7833281







