

Remington Arms Co., Inc.
Product Service
Legal Case #:5451

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
214798	12/15/2010	12/16/2010	12/16/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gunworks of Central NY	---	Gunworks of Cen	5378 St Rte 31	Verona	NY	13478		W 315-363-7041

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C	Unexplained Discharge			

Dealer brought gun to factory. They stated the gun fired without pulling trigger. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/257 ROBERT	84020	S6696147	PD	6/1/2009 5:06:18 PM

Date Purchased	Where Purchased	Accessories	Original Owner
	ELLETT BROTHERS, LLC	SCOPE,RINGS,TWO PIECE BASE	U

CONCERN:FIRED WITHOUT PULLING TRIGGER

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Check over & test under warranty						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$27	1/7/2011				

Per Ilion - Could not duplicate concern. TA functions as designed. Check over completely, clean & test fire @ n/c - warranty. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/16/2010
	Product Type		RF

	Action Type	A
	Assigned To	T.NAGLE
Cause	4038	Could Not Duplicate Concern
Barrel	Description	24" 257 ROBERTS
	Date Code	PD
	Bore Plugged	False
	Bulged	False
	Fired	False
	Fired while Obstructed	
	Muzzle/Crown Condition	Slightly Worn; Functioning
Bolt	Firing Pin	Slightly Worn; Functioning
	Shroud	Slightly Worn; Functioning
	Face	Slightly Worn; Functioning
	Handle	Slightly Worn; Functioning
	Stop	Slightly Worn; Functioning
Extractor	Condition	Slightly Worn; Functioning
	Cut Condition	Slightly Worn; Functioning
	Ext/Eject Test	False
Locking	Block Condition	---Select---
	Lug Condition	Slightly Worn; Functioning
	Notch Condition	---Select---
Overall	Exterior Condition	Slightly Worn; Functioning
	Stock Condition	Slightly Worn; Functioning
	Fore End Condition	---Select---
Receiver	Condition	Slightly Worn; Functioning
	Bulged	False
Safety	Description	STANDARD XMP SAFETY
	Function	Like new; Functioning
	Sub-Assembly	Non-ISS
Sear	Lift	---Select---
	Notch	Like new; Functioning
	Tests	Test Fired
Feeding Test	False	False
Trigger	Condition	Like new; Functioning
	Pull	---Select---
	Altered	False
	Sub-Assembly	X-Mark Pro
Non-Remington Components	Description	SCOPE,RINGS,TWO PIECE BASE

Receipt Of Firearm(s) Delivered to the Plant for Repair
Firearm Checked For Live Ammunition ☒

File No 5987

Delivery Date 12/14/10 5451Customer Name (Print) The Gun Works of CNYAddress 5378 ST. RTE 31City VeronaState NYZip 13478Phone Number (315) 363-7041Fireman Description Model 700Cal./Ga. .257 RobertsSerial Number 56696147

Stock/ Fore-end Condition circle the description

(Excellent Good Fair, Poor, Fancy, Plain, Synthetic, Wood)

Comments on Stock/ Fore-end condition _____

Metal Condition circle the description

(Excellent Good Fair, Poor, Fancy, Plain Stainless Steel)

Comments on Metal condition _____

Barrel Type (VT. Rib; Plain; Deer; Stainless Steel) Barrel length _____

List additional accessories IE Scope, Sling, Gun case and description;

Scope - Bushnell 3x9Customer request: See ATTACHED - Gun fired w/o pullingReturn Process Return to Clark St. Ent. ☐ Return via UPS ☒

By signing this receipt the person delivering the firearm understands to be the only person to receive the firearm upon completion of repairs.

Signature Larry Chandler

person delivering firearm

Date 12/14/10Signature Ann L. Bentley

security officer

Date 12/14/10Signature Gaul Thomas

arms service / CSR

Date 12/15/10

Customer Pick Up Verification

delivered the above described firearm to the
ay lawfully possess a firearm in New York State.

Date / /

t be the same who delivered

Date / /

ss returning the firearm

S6696147

Model: 700

BY:.....



RE00214798

Remington.

BARBER - Kinzer PPS GAL RE 0013550

Security Copy - White

Arm Service Copy - Yellow

Customer Copy - Pink

PS 15438

could not duplicate concern
T.A. functioning as designed
check over completely, clean
+ Test Fire AT 14/10
unhappy why

24"
PD 6/0'
2#

THE GUN WORKS OF CENTRAL NEW YORK

5378 STATE ROUTE 31

VERONA NEW YORK 13478

CNYGUNWORKS@HOTMAIL.COM

PH: 315-363-7041

FX: 315-280-0841

REMINGTON :

DEC 13-2010

**PLEASE REPAIR AND SHIP BACK TO ABOVE
ADDRESS. THANK YOU.**

GUN FIRED WITHOUT PULLING TRIGGER

THANK YOU

REPAIR # 078087

SERIAL NO. S6696147

ANY QUESTIONS PLEASE CALL.

WE THANK YOU FOR YOUR TIME IN THIS MATTER.





