Page 1 of 3

BARBER - Kinzer PPS GAL RE 0013711 Remington Arms Co., Inc.

Product Service Legal Case #:5051

Case Information

Date Opened(PS) **Date Closed** RE# **Date Opened Incident Date** Pre Lit Lit Obsolete 212058 12/2/2010 11/10/2010 1/14/2011 11/8/2010

Customer Information

Business First Name Last Name Street Type City State Zip Age Contact

3007 Peavine Fire Tower Rd Crossville TN 38571 Incident Ronnie Smith

3401 Manassas Rd Reporter James Harris Cookville TN 38506 C 931-260-3598

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD shot truck engine

Cause: 4038 Could Not Duplicate Concern

Fires on safety release

Concern: 1007 Fired on Safe Release

Unknown

C

11/10/10 Rec'd voice mail from Harris stating that he had a VTR .308 and he has just returned from a trip and it fired when safety was released 3 times. On the 3rd time it shot through the floorboard of the truck, 11/10 2:50: Spoke with Harris, a couple of the officers where he works bought VTR's since they use LTR's on the job. Was going to shoot at a deer, took the safety off and it fired. He thought he made the mistake so he and his friend go to another area, a doe comes up and he gives his rifle to his friend to shoot. His friend takes that safety off and it fires. He takes it back to the truck, pulled out the fired shell and put another round in the chamber and it fired and put a hole through the engine. He stated that it has a "hair trigger" and he hasn't adjusted it. It came from the factory that way. He's been a cop for 17 years.cm

Firearm Information

Mfg. **Type** Model/Ga. SKU Serial Bbl. **DOM** 700/308 WIN Remington CF/BA 84371 G6901554 9/15/2009 8:51:31 PM

Where Purchased **Date Purchased** Accessories **Original Owner**

SPORTS SOUTH LLC Y

Ammunition Information

Mfg. Cal./Ga. SKU **UPC** Type DOM Mfg. Code /150 Winchester Other Concern **Factory** Reload 0: Y Supreme SilverTip N

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Cash Reim. Date Settlement Release of Claims Release Date Reimbursement Date Settlement APV APV Refund for truck repair and repair 910.95 1/14/2011 700 at no charge

> Repair/Replacement Repair/Replacement Cost Date

62.40 1/14/2011

11/10/10 Mailing ARS and letter.cm 12/7/10 D. Evans said ok to refund for truck repairs. Called Harris and let him know we

PrintDisplay

BARBER - Kinzer PPS GAL RE 0013712 would refund for repairs and repair 700 no charge. Awaiting receipt for repairs.cm 12/21/10 Mailing release to truck owner, Ronnie Smith.cm 1/14/11 Rec'd signed release. Processed G408 for refund of \$910.95.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		supry
	Exam Date		12/3/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		Supry
Cause	4038	Could Not Duplicate Concern	Could not get this to fire without pulling the trigger
	Description		22 inch Model 700 VTR 308 caliber
	Date Code		DD
	Bore Plugged	False	
Barrel	Bulged	False	
Burter	Fired	False	
	Fired while Obstructed		
1 1	Muzzle/Crown Condition	Like new; Functioning	
	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
Bolt	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
	Condition	Like new; Functioning	
Extractor	Cut Condition	Like new; Functioning	
	Ext/Eject Test	True	
	Block Condition	Select	
Locking		Like new; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Like new; Functioning	
	Exterior Condition	Like new; Functioning	·
Overall		Like new; Functioning	
	Fore End		

BARBE	R - Kinzer PPS GA Condition	L RE 0013713 Select	<u> </u>	1.000
Receiver	Condition	Like new; Functioning		
	Bulged	False		•
	Description]	Model 700	
Safety	Function	Like new; Functioning		
Sear	Lift	Select	.013"	
	Notch	Like new; Functioning		
Scar		Condition	Like new; Functioning	With the safe arm in the null position and repeated pulling of the trigger the safe would move to th
Pull	Trigger	Select	2.5 lbs	
Altered		False		
Sub- Assembly		X-Mark Pro		

12/08/2010 at 10:24 AM 30161

Job Number:

JULIAN'S AUTO BODY AND FRAME

Family Owned and Operated 1702 South Jefferson Ave. Cookeville, TN 38506 (931)372-0102

PRELIMINARY ESTIMATE

Written By: Matt Julian Adjuster:

Insured: Ronnie Smith

Owner: Ronnie Smith

Address: 3007 peavine fire tower rd.

crossville, TN 38571

Day: Evening:

Claim # Policy #

Deductible: Date of Loss:

Type of Loss: Point of Impact:

Inspect Location:

Insurance

Company:

Days to Repair

2005 FORD F250 4X4 SUPERCAB 8-6.0L-TD 4D LONG Int:

VIN: UNK

Intermittent Wipers

Power Steering FM Radio

Anti-Lock Brakes (4) 4 Wheel Disc Brakes

6 Speed Transmission Styled Steel Wheels

Lic:

Dual Mirrors

Power Brakes

Driver Air Bag

Rear Step Bumper

Stereo

Prod Date:

Odometer: Clear Coat Paint

AM Radio Search/Seek

Passenger Air Bag Trailering Package

4 Wheel Drive Overdrive

NO.	OP.	DESCRIPTION	QTY	EXT. PRI	CE LABOR	PAINT
1#	Repl	CARPET CAB	1	532.53	4.0	
3*	Rpr	Floor pan assy manual trans			1.0	0.0
		Subtotals ==>		532.53	5.0	0.0

Parts Body Labor	5.0	hrs	@ 	\$	40.00/hr	532.53
SUBTOTAL Sales Tax	\$	732	. 53	<u>@</u>	\$ 9.7500%	732.53
GRAND TOTAL			-		\$	803.95

ADJUSTMENTS: Deductible

0.00

<u> </u>	ን ግ	_	2			_	•		ر ارد	<u>-</u>	-	<u>_</u>
o	0		D						NT	<u>.</u> 5 '	10	-
Ò	ì	<u>-</u>	٥				प्रपा उरा	SAL KE	BARBER - MILKE UNISTIS		BER -	***************************************
Harymade.	And Boynelds	Harywolde and Demode TO BROSE: wateringsoutherent 1-601-34-0984: Dr 1-400-531-0056	SOUIDAZENTE I-BOP-34	14-0994: Da 1-600-5	3200-123		٠	 . 				! !
			DEPT	COOKEVILLE POLICE DEPT	VILLE	C00KE		863	2010 13:30 FAX 8315207863	FAX	13:30	010

ĺ	OÙ4H.	PART NO	NAME OF PART		SALE	NT	340.00		LEROY'S SERVICE STATION 184 S. Roy MoNair Blvd. 1.44 27 Y. SC 205500 (643) 394-2741 01432	
*/****	· · · · ·						•	-	LAKE CITY, SC 29580 01432	7
.[` `		ļ .	- 7		· Vi	85.	•	(843) 394-2741	- #:
].			_		1		1	Ţ	DATE RECEIVED 611-08-	JB
[•			•				· <u>70</u>
	<u>.</u>							7	DATE RETURNED 11 . 09 -	<u>com</u>
			<u> </u>			1		-31		ار
	' .		:"			• ;			STATE ZIP	<u></u>
4	•	· :	·	$\overline{}$	 			-	88670 8868 UPTSY21955F C 3/4	5 5
ADDITIONAL				-, (.					MARE MIGHE STATE	′′፟፟፟፟፟፟፟፟፟፟
Ĕŀ				44	├ ──┼			<u> </u>	2.05 / Farch 144766 Tenn	—₹
ğ						<u>.</u>		1	OPER NO. INSTRUCTION AMOUNT	<u>т Д</u>
	<u> </u>	V		•			_/		LUBRI- CHANGE CHANGE WASH POLISH DIFF.	Ä
			<u>, </u>	$\perp \perp$			f		CATE OIL TRANS, DIFF.	
Omeny ries.		<u> </u>		Λ	Q	ند	1		Hoof IDs to Check No-Start	<u> </u>
١٤٤		··:	11/00	1 N	1	į			Condition	_9
1 8		, , , , , ,	111	_						
N S				***		***	40.0		Genou Strato House and Sideal	75
	*** " " " " " " " " " " " " " " " " " "	-							Jacobs Toolton Leed Source	
5			<u> </u>				Ž.			
			<u> </u>				+		The state of the s	-
<u>~</u> }⊦		SUBLET			-	-7.7	-			
2							 - j	.		
ES:		ACCESS.	 	}						
¥						_		. 30		
STIMATE			<u> </u>				-4			
							111	À	If hereby authorize the repair work herein set orth to be done by you, together with the furnishing by you of the necessary parts and other material for such repair, and egree: that you are not responsible for any delays caused by unavailability or delayed availability or larts or material for any reason; that you neither assume nor authorize any other person to assume for you any leability in confection with such repair; that you shall not be responsible; to loss of or damage to the above vehicle, or articles left themen, in case of firs, theft or other cause beyond your point of the above vehicle or of the themen of the above vehicle on the above veh	00
			OTAL PARTS			<u>·</u> 1		1	and other magnial for such repair, and egree: that you are not TOTAL PARTS	
		GALS GAS	<u> </u>				1		availability of leafs or material for any reason; that you neither GAS, Oil, GREASE	
		QTS. OIL	<u> </u>			_		•	Bability in conflection with such repair; that you shall not be ACCESSORIES	
	(*) 	LBS. GREASE	`\						responsibles of loss of or damage to the labove vehicle, or TIRES, TUBES	
g .		TOTAL GAS - OIL				ڭ_		: <u> </u>	your control light an express mechanic's fien is hereby acknowl SUBLET WORK	
ξ	THE	IO SELLER HEAED	SCLAIMER OF WARRAN Y: EXPRESSLY DISCLI	NTIES: Alms	ALL V	HAN	HANT	IES.	thereto; that your employees may operate the above vehicle on storal.	01
ğ.	EITHE OF M	REXPRESSED OF	SCLAIMEN OF MARKAN RIMPUED, INCLUDING V OR FITNESS FOR A ES NOR AUTHORIZES LIABILITY IN CONNEC	ANY I	MPLIE	DW/ NA P	MRAI	NTÝ ISE	stroets, fighters or elsewhere for the purpose of testing and/or inspecting specimenical.	
2	AND	NEITHER ASSUM	ES NOR AUTHORIZES	ANY	OTHER	CHE	RSON	TO		-
õ	SAID	PRODUCTS.	Separate to dolar co						X TOTAL AMOUNT 107	00

+803.95 9/0.95

ORIGINAL

Remington Arms Company, Inc.

Madison, NC 27025

Purchase Order No.	Seller's	s Invoice No.		Seller's Invoice Date			
Christy Mitchell						·*····	
Name of Person Originating APV	Pay To):	Ronnie Smith	<u> </u>			
Consumer Ext 8684 Location/Extension of Originator 1/14/2011	Street	and No	3007 Peavin	e Fire Tower Rd			
Date Prepared	City	Crossville		State TN	 _	Zip Code	38571
%Days; NetDays or	<u> </u>			Vendor Code	106248		
	Desired Pay Date]		Pmt Method			
					<u> </u>	Total	
Description	refund	for repair o	truck			ollars	Cents
Reimbursement for truck repair per C. Mitc	hell					910	.95
Ref# 38571SmithRonni		Repair#	212058				
		Case #	5051				
Wire Transfer Information							
Bank:	***						
ABA:					ļ		
Pay to:		, , , , , , , , , , , , , , , , , , , 		<u> </u>			
Acct #:							
Distribution	The app	proval signature	s) shown below at	test that all required	Gross		
	_ []		•	operly made and that	((910	05
Tax	ŧ	as to correctnes		nents without further	Discount	310	.93
	Signe	ed:					
	Signe	ed:			Net		
	Date:		1/14/2011			910	.95
	\			1 N			
For Treasury Use Only							
Date Paid							
Reference No.							
Bank Acct							
USD Amt							
(If in Foreign Currency)				•			

GENERAL RELEASE

KNOW ALL PERSONS BY THESE PRESENTS:

That I Ronnie Smith , having an address at 3007 Peavine Fire Tower Rd, Crossville, TN 38571 , being of full age, in consideration of and upon receipt of a check in the amount of \$910.95 for repair of the 2005 Ford F250 sent as a gesture of goodwill ("Consideration"), do hereby release and forever discharge REMINGTON ARMS COMPANY, INC., its parent and affiliated companies and its/their predecessors, successors, assigns, employees, officers, agents and directors ("Releasees") from all debts, claims, demands, damages, costs, expenses, actions and causes of action what-so-ever nature or kind, known and unknown, on account of, resulting, or which may result from an incident occurring on or about November 8, 2010 which I have alleged was caused while using products manufactured and/or sold by Releasees.

I further state that receipt by me of the Consideration described above constitutes a full and complete settlement of the claims described above, that this release is a compromise and is not to be construed in any way as an admission by the Releasees of any responsibility for the incident, or for an alleged defect in said products or that any such defect exists.

I acknowledge that I have carefully read and understand the contents of this release and sign the same as my own free act.

IN WITNESS WHEREOF, intending to be bound hereby, I have hereto set my hand this day of \(\int \text{O(N)} \text{O(N)}, 20 \(\text{O} \text{O} \).

Notary signature: __

Print Name

Signature (Ronnie Smith)

Products (serial numbers):

G6901554

VIN1FTSX21P55EC31099

Social Security Number or Driver's License #

Response Vale.

PS 15605

BARBER - Kinzer PPS GAL RE 0013718

	Case #	5051	Date of Call	11/10	Date of Incident	11/8	PreLit A. Lit	Obs	
)	Reporter name address				Incident Name/Age address	Ja. 340	mes Har I hanassas Ville, TN - 1-260-3	ris- Rd./Co	p for
	contact #'s				contact #'s	Cook 93	(ville, TN = 1-260-3	598	
	email				email				
	Injury Medical								
	Treatment Alleged cause								
	Firearm	Ser# (-690/554	Cal . 308	DOM	Orig owner?	When/W	here purchased	JTR	
) Ì	Ammunition	Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot#	Additional info	Silve I	~, <u>.</u>
	Other Product					<u> </u>			P -
		pushed	safety uck, 1)	noted	stell	out, c	They bought fred, doe fulled Cycled and	ther in	-
	Notes: Customer's	1 1 T 41	red, I	to wheat	a har	it;	loger on it.	pull.	
. -	Request								
	My actions/ offers					BARBE	ER - Kinzer PPS G <i>l</i>	AL RE 0013718	



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE: 11/10/2	2010 REQUESTED BY:	christy	
QUANTITY:	1 WEIGHT PER PACKA	AGE:	10
PLEASE CHECK ONE			
MEDIA			
COORDINATOR		xxxxxxxxxxxx	
TO MAIL	I WILL MAIL		
DESCRIPTION:			
	700		
G6901554			

LABEL INFORMATION

MAIL LABEL TO:	James Harris 3401 Manassas Rd Cookville, TN 38506	
	=	
RETURN ITEM TO	Rem Prod Serv Ilion, NY	

PLEASE COMPLETE ALL PARTIS OF THIS FORM: AND SEND TO THE MEDIA COORDINATION

4XX596 SVC GNDCOM TRACKINGH 1Z REF 1:JAMES REF 2:700/G6	HARRIS/CL	ACT 1 71137	ט. פו דנ	CURR	USD	1 06	1
HANDLING CHA SINGLE-PTECE DV 0 00 DC 0.00 AH 0.00 TOT PUB CHG	PUB RATE	E CHRE COD DGD PR	6S: 0.00 0.00 0.00 PUB+HA		RS SD SP	T/P USD 0.50 0.00 0.00 8.74	

AHNO CHRISTY MITCHELL

FAX: 336-548-7872

FROM 8 JAMES HORRIS

3401 Manassas RO

Cookeville, TN 38506

ph# 931-260-3598

BARBER - Kinzer PPS GAL RE 0013721

्रfrmRepairMain - FGI Repairs	
File Add Repair Estimate Repair Expedite Repair Inquiry	Repair Tools CSR Tools Reports Table Maintenance System Location
图frmREInquiry - Repair Inquiry	
Repair Number: PE 0021 2058 Serial: G6901554 Model 700 Center Fr 308 W/N Produced: 03/15/2009 SKU: 8	4371
Vaily Repail	Status: Parked 12/3/2010 8:56:13 AN
ADDRESS INFORMATION Customer,	Return To C Received from
Name: JAMES HARRIS	JAMES HARRIS
Addless 1: 3401 MANASSAS FIDAD Addless 2: P0 Box	3401 MANASSAS ROAD
CIV COOKEVILLE	COOKEVILLE
State: TN - Zip Code 38506 Country: US	TN Zip Code 39505 Country US
FFL 「	
Contact / Condition Problems Estimate: History / Status Shapping / Billing	
2 / C	Desc? C Shapping Hold Current Status Parked Parke
12/1/2010 9:3: New valentds Repair Added 12/1/2010 9:4. Update valentds Repair information change	
	HARRISZIE Patts Received Check In:
12/1/2010 12 Email/erified ArmEmail Receipt J	HARRIS20 Passed Inspection LUN Return as Received Current Location
12/3/2010 8:5. ParkedExt. supryfl Placed in PS Back Rack F	lolding for d THas Been Approved
	C Internal Repair Transfer Number
Repair Search	Refresh Close Since
	and the second s
•	
supryfi - ILN/Prod frmRepairMain	D1102R7XPIL Friday, Dec 3 2010 10:29 AM
Property of the state of the st	Offinegramman Fig. 2007 PM 110 PM

12/1 Danny of a reimbursing for track.
He will fox receipt for truck repair.

	EC	رکے کا		
	DEC		2010	
В	Y:			

BARBERI-PKinzer PPS GAL RE 0013722 null position safety walks forward until discharge with repeated pulling of the trigger.

Could not get the gon to fire unless the trigger was polled.

November 10, 2010

we should offer to settle this with customer - replace trigger assembly and pay danges TRED 12/3/10

James Harris 3401 Manassas Rd Cookville, TN 38506

Subject: #5051, Model 700

Dear Mr. Phillips, 5

Per our phone conversation, enclosed is the prepaid UPS ground shipping label for shipment of the firearm to our factory for inspection. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mit Consumer A Phone: 800christy.mitc

₿G6901554

Model:

RE00212058

enclosure

DEAR REMINGTON,

As I mentioned on one phone conversation, I DO HAVE DAMAGES TO A VEHICLE DUE TO THE DEFECT of my RIFIE. Please Consider the danger of \$1,075 of that occurred when my Ritie Duchararo. LUCKILY NO ONE WAS HURT!

SINCERRLY, JAMES HARRIS

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

BARBER - Kinzer PPS GAL RE 0013722


Model:

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700 VTR	Serial Number: G 6901554					
Are you the original owner?: YES NO						
Name: JAMES HARRIS ->	Date of Purchase: NOVEMBER 2009					
Address (no PO Boxes): 3401 MANASCAS ROAD.						
city: Cookeville	State: 70 Zip: 38506					
Phone (Daytime): 931 - 260 - 3598	Fax:					
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) Sharris 205@ hotmail.com						
E-mail Address:						
I would like to receive future e-mail updates from Remington.						
Please describe your problem and date of occurrence: THE GUN DISCHANGED THREE TIME, AS YOU PUSH THE SHEETY OFF, WITHOUT PULLING THE TRIGGER. THE THIRD TIME THE GUN WENT OFF, ZT DISCHANGER WHEN A SHELL WAS Chambered + THE BOLT LOCKED. FT THEN FINED ON IT'S ON ShootING THROUGH THE FLOOR BOALD OF Ahetruck.						
Ammunition Information: WINCHESTER						
Manufacturer: WIN CHESTER	Type: Supreme					
Other (i.e. bullet weight/type, shot size, powder):						
· · · · · · · · · · · · · · · · · · ·	\					
01554 700	Powder Weight: Primer Used:					

_





Trig Waiver?

Roth

Nayle / supry

Balic

Nick.

Evans dus

BARBER - Kinzer PPS GAL RE 0013725

Warning Ltr if they won't sign. Documenting