

CAL: 300 WIN MAG

PROJECT # 241314

BARBER - 5.22.06r0003637

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS
SW/PR	12/19/03	Out of box Inspection			
JS	12/22/03	De-torque Scope Cross Bolt Screws	Front 35 Rear 30		
BL		Head space	min 7.002		
BL		Proof	OK	1	1
BL	12/22/03	Head space	min 7.003		
JS/BL	12/22/03	Depth Front Take down Scope	kale		
BL	12/23/03	Firing Pin Indents	.0215 .021 .021-Aug .021		
JS	12-29-03	Seal/Trigger Engagement	Arg. .0292		
JS	12-29-03	Seal lift	.0178		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min + .004		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Head space after proof	Min + .004		
B.Lee	1/15/04	200nd JAC Funct. test	magazine approx hand to take from magazine well / 7FTE Bolt hand to close	200	202
SW	1-15-04	Head space	Min + .005		
BL	1-16-04	Shoulder Fine	ok	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

Confidential - Subpoena to Produce Documents - Order

Williams v. Remington

ET20016

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-24

TLW #: TLW1303

Date: 01/20/10Inspector: JS/BLRound Level: 222☒ Measure Headspace min + .004☒ Sear Engagement: 1st. 0282 2nd. 0278 3rd. 0284Ave. 0281 spec. .020" to .025"

Respt. Eng

☒ Trigger Pull: 1st. 4.477 2nd. 5.509 3rd. 5.271Ave. 5.086 spec- 4 lb. to 5.5 lb.

.0247

☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area.☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: locking lugs some wear, bolt stop some wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine Box protruding

TLW1303

Remington Confidential

ET20017